
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

None



Survey 95-74 calls setting "IP" at corner point.

No record of subsequent monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Found 5/8" iron pin (rebar) as per survey 95-74.

See Union County survey 002-1994.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

The true corner position bears N 85°E, 2.10 feet. An additional monument was not set.

The bearing trees are referenced to the found 5/8" iron pin.

A 15" Douglas Fir bears N18°E, 56.06 feet, marked "S 1/16 S7 BT".

A 9" Douglas Fir bears S23°W, 6.44 feet, marked "S 1/16 S12 BT".

Drove steel fence post 5' north of the 5/8" pin.

I hereby certify that the above corner point was perpetuated as hereon described on January 25, 1994. Witness: Jeff Petersen, Mike Schlegel.

UNION COUNTY
SURVEYOR

Date Received 2-10-94

Date Filed 3-17-94

By Myny T. Slack

File No. 010-1994-R

PROFESSIONAL
LAND SURVEYOR

OREGON
DUANTE L GRIFFITH
644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 20° East magnetic declination and the distances are to a 60d nail driven into the right side of the root crown.