CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

None.

T 2 N R 39 E J-22

DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

See Survey 011-2019

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At the position by survey I set a 5/8"x30" iron pin, 5" above ground, with 2 $\frac{1}{2}$ " aluminum cap marked as shown below, from which:

NEW BEARING TREES:

A 3" Douglas Fir bears South 17° East a dist. of 9.35 ft., marked W 1/16 S13 BT. A 5" Douglas Fir bears North 32° West a dist. of 9.75 ft., marked W 1/16 S12 BT.

South/East fence corner falls South West of monument approx. 30 ft.. Set steel fence post South approx. 2".

I hereby certify that the corner was monumented on May 17, 2019. Witness: Kyle A. Tucker.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFREY S. HSU

Renewal Date: June 30, 2019

83571

UNION COUNTY
SURVEYOR

Date Received 5/28/19

Date Filed By 1/26/1/2019 R

File Number 034-7019 R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. The bearings are to a brass washer marked OPLS 83571 attached to the BT blaze of the new bearing trees.