CERTIFIED RECORD OF LAND CORNER MONUMENTATION

CORNER MAINTENENCE

History of original corner establishment:

Corner established by Henry Meldrum under GLO contract no. 450 dated June 11, 1882.

Surveyor General records state:

Set post 4 ft long 4 ins square 24 ins in ground for Cor to Secs 14, 15, 22 & 23 marked: T 2 S S 14 on NE, R 37 E S 15 on NW, S 22 on SW, and S 23 on SE with 3 notches on S and 2 on E edges from which:

DIA	DIAGRAM			
		R 37 E		
S	15	S 14		
S	22	S 23		

A fir 20 ins diam bears N 44° W 22 lks dist marked R 37 E S 15 BT.

A pine 15 ins diam bears N 28° E 20 1ks dist marked T 2 S S 14 BT.

A pine 15 ins diam bears S 53° E 13 1ks dist marked S 23 BT.

A pine 10 ins diam bears S 42° W 17 1ks dist marked S 22 BT.

This corner was remonumented by Anderson-Perry & Associates in 1977 with a 3 inch brass cap on a 2 inch iron pipe. No new bearing trees were established.

Description of corner evidence found:

Found a 3 inch brass cap on a 2 inch iron pipe projecting 4 inches out of the ground marked thus:

T 2 S R 37 E WM

APA

Found a sawed and rotted stump for section 22 bearing tree with a portion of the letter B scribe remaining.

Found a root hole with rotten wood for section 23 bearing tree.

No trace of sections 14 and 15 bearing trees. Description of monument and accessories lestablished to perpetuate the

original location of this corner:

Built a surrounding rock mound around existing corner monument and set a 6 foot steel fence post alongside with a sign 54-4 attached.

New bearing trees established:

A tamarack 8 ins diam bears S 26° E, 9.4 feet dist marked T 2 S R 37 E S 23 BT.

A fir 9 ins diam bears S 20° W, 45.0 feet dist marked T 2 S R 37 E S 22 BT.

A fir 8 ins diam bears N 15 $^{\circ}$ E, 11.0 feet dist marked T 2 S R 37 E S 14 BT.

A fir 11 ins diam bears N 11° W, 41.1 feet dist marked T 2 S R 37 E S 15 BT.

Each new bearing tree has a sign 54-3 attached below a 6 inch band of red paint and a brass washer marked PLS 1639 nailed flush with BT blaze. A sign 54-4 is attached on opposite side of tree from BT blaze.

I hereby certify that the above described corner monument was properly maintained to Forest Service standards by me on Sept. 25, 1983, and witnessed by Jim DeMastus and Tom Fisk.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William L. Hanley
OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of County Surveyor	County of
State of Oregon , I hereby certify to	hat the within instrument was filed in this office
for record on the day of	
by	, ,,,,,,,
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

Date Respired 9-28-83

Date Filed 9-28-83

By G. LANGLITZ DEPUT
File No. 372-83 R

UNION COUNTY SURVEYOR