UNION COUNTY SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT


Survey No. 67-75 calls an existing fence the North line of the Southwest 1/4 of the Southwest 1/4 without breaking the Section. I found a monument set near the true Southwest 1/16 of Section 9 but do not accept it as the Section was not properly subdivided.

No record of subsequent monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Found monument by Survey 67-75, did not accept. Position determined by Survey No. 73-78.

T2S R38EH-10



See Survey No. 73-78

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by Survey No. 73-78 I set a 5/8" x 30" iron pin with a 2" aluminum cap, marked as shown below, 30" in the ground from which:

A 5/8" x 30" rebar bears N8°59'E, a distance of 37.28 feet.

A 5/8" x 30" rebar with 1 ½" aluminum cap bears S59°38'E, a distance of 6.59 feet, marked BGB SURVEY MARKER SOUTH RP.

I set a steel fence post approximately 1 ft. North of the monument.

I hereby certify that the corner was monumented on January 5, 2001 Witness: Norbert W. Volny and Rick G. Robinson.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON July 17, 1986

RICK G. ROBINSON

2219

Renewal Date December 31, 2002

T2S R38E

SW 1/16

•
S 9

2001
OPLS 2219

UNION COUNTY SURVEYOR

Date Received 2/12/01

Date Filed $\frac{3/2}{\rho}$

Ju. 1 de -

File Number 001-2001 R

I used a Leica 500 GPS unit in the establishment of the new accessories. The Basis of Bearings is the same as that on Minor Partition for John Melland. The distances are to the center of a 5/8"x30" rebar.