CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original comer establishment:

None. Corner established with this survey.

G-15 DIAGRAM T 2 S R 40 E C 1/4 • S 10 1989 ORLS 1639

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position established by proper subdivision of section from survey control...

Set a 2" x 30" aluminum pipe with $2\frac{1}{2}$ " aluminum cap 25" in ground & projecting 5" out of ground with surrounding earth mound & placed 6' steel fence post alongside with signs 54-2 & 54-9 attached. Cap marked as shown in corner diagram. No stones available for mound.

New bearing trees established: Western larch 16" dia brs N25°E, 41.1' dist mkd C 1/4 S 10 BT. Western larch 13" dia brs N79°E, 27.0' dist mkd C 1/4 S 10 BT.

New bearing trees have a brass washer marked PLS 1639 nailed flush to face of blaze. Attached signs 54-3 & 54-9 & painted face of blaze & a 6' band of red around each bearing tree.

Compass declination 190 East.

I hereby certify that the above described corner monument was properly established by me & witnessed by F.S. Munro on October 02, 1989.

REGISTERED **PROFESSIONAL** LAND SURVEYOR William L. Hanley OREGON JULY 14, 1978 WILLIAM L. HANLEY

Office of County Surveyor County of State of Oregon , I hereby certify that the within	•
for record on the day of by	UNION COUNTY SURVEYOR
R6-7100-57 (9/71)	Date Received 3-12-90

Form F

*GPO-591-971, 1988