
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T3N R39EN-20



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

See Survey Number 031-2021

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8"x30" iron pin, 28" in the ground, with 2 1/2" aluminum cap marked as shown below, from which:

NEW BEARING OBJECTS:


A 5" Douglas Fir bears South 45° East a dist. of 42.95' marked E 1/16 S23 BT

A 3" Douglas Fir bears North 40° West a dist. of 43.15' marked E 1/16 S14 BT

Set steel fencepost Southeasterly approx. 1 ft. A fence corner from which fences bear North, South, and West bears South 29° West approx. 9'

I hereby certify that the corner was monumented on June, 21st, 2021.

Witness: Kyle A. Tucker, Emmitt A. Ambert



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2023

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

UNION COUNTY SURVEYOR	
Date Received 7/15/7/	
Filed By Mit GMin X	PTTY
File Number 078-7021 R	

N-20