CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not set.

Inde	ex	File	No.	V-4	
		DIAGRA T41		ΟE	

Description of corner evidence found:

Hone.

Some red painted line trees N.E. of corner position.

Corner falls at South edge of uncut timber on N.W. slope.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set $2\frac{1}{2}$ " x 30" galvanized pipe with brass cap marked: Set pipe 24" in the ground.

No rock in the area.

T4N R40E \$30 E \$31 1/16 OR PLS 1051 1978

File No. 100 - 83R

From which: A Fir 12" in dia. bears N15°W, 35.8 feet, scribed E1/16S30BT. A Fir 14" in dia. bears S54°E, 33.3 feet, scribed E1/16S31BT. Painted blazes red and 6" red band around. Placed 54-3s and 54-4s on BTs. Placed brass washer stamped PLS 1051 on foot blazes. Placed 54-2 and 54-4 on steel fence post 3' Horth and 54-2 and 54-9 on steel fence post 5' East of corner. Placed 54-5 on large tree 8' North of corner.

PROFESSIONAL LAND SURVEYOR

OREGON OCT. 17, 1975 EARRY B. BARBOUR 1 0 5 1 I hereby certify that the above corner monument was reestablished as herein described.

Witnesses:

David L. Landers

Dan T. Rowland

November 1, 1978

State ofOregon , I hereby certify that the within instrument was filed in thi for record on the 20. day of No.vembor		
(DEPUTY)	Proposition to with the contract of the contra	
Form R6-7100-57 (9/71)		
	Date Filed	
	, 19 .7.8 	

History of original corner establishment:

Corner was established by OR PLS 1051 in 1978. Set: At surveyed point set $2\frac{1}{2}$ "x30" gal. pipe with brass cap 24" in ground. Marked: 12" Fir N15W, 35.8'- 14" Fir S54E, 33.3'.

DIAGRAM				
E	1/16	<u>\$30</u> \$31		

Description of corner evidence found:

2" gal. iron pipe with a $2\frac{1}{2}$ " brass cap firmly set 6" above ground. Stamped:

1978 14" now 16" Wh. Fir $S56\frac{1}{2}E$, 33.3' (record S54E) Scribing visible on double blaze. 1978 12" Fir now 12" Spruce N15W, 35.6' (record 35.8') Scribing visible on double blaze. Guard post East with 54-2 and 54-9 signs.

T4N R40E $E \frac{\$30}{\$31} 1/16$

OR PLS 1051 1978

Description of monument and accessories I established to perpetuate the original location of this corner:

Nailed 54-9 and 54-3 signs to BT's and painted bands and blazes red. Set guard post West with 54-2 and 54-9 signs.

Dec. 20.

Witnesses: Norman Larson and Carole Bishop.

Work was done in June 1994.

SURVEYOR
Data Received 9/27/24
Data Filed 10/22/24
By Gryn T. Hak
File No. 069-1994R

PROPESSIONAL
LAND SUEVEYOR

Fry J. Buring

OREGON
LARRY D. BISHOP

EXPLISES 12/31/95

Office of	County of
State of	, I hereby certify that the within instrument was filed in this office
for record on the day of	
4-4-4-4	by
(COUNTY OFFICIA	AL) (DEPUTY)

Form R6-7100-57 (9/71)

GPO---798-276