CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by David Thompson under GLO contract number 103 dated September 3, 1863. Surveyor General field notes state:

Set post for 1/4 sec. corner in mound of earth with charred stake, pits, trench, as per instructions.

T4S R40 ER-11 S 21

DESCRIPTION OF CORNER EVIDENCE FOUND:

None found. Position falls in a formerly tilled field.

See Survey 005-2020

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At proportionate position I set a 2 1/2" aluminum pipe with 3" aluminum cap, 28" in the ground and marked as shown below, from which:

NEW BEARING OBJECTS:

A 5/8" x 15" iron pin bears North 30°12' East a dist. of 24.50 ft., marked NE RP. A 5/8" x 15" iron pin bears South 48° East a dist. of 21.60 ft., marked SE RP. A 5/8" x 15" iron pin bears South 19°25' West a dist. of 18.30 ft., marked SW RP. A 5/8" x 15" iron pin bears North 52°50' West a dist. of 24.33 ft., marked NW RP.

REGISTERED **PROFESSIONAL** LAND SURVEYOR OREGON

83571 Renewal Date: June 30, 2021

JEFFREY S. HSU

T4S R40E S21 1/4 **S28** 2020 OPLS 83571

UNION COUNTY SURVEYOR

I used a Leica GS 18 in the establishment of the new accessories. Basis of Bearing is as per Survey 005-2020, the distances and bearings are to the center of the aluminum caps.