CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Thompson and Chaplin surveyed the easterly portion of T. 6 S., R. 38 E., W.M. under GLO contract No. 104 dated April 16, 1864.

Record states:

Set post for corner to secs 2 & 3 in mound of earth with charred stake, pits, trench & as per instruction.

		A-	-17		
DIA	GR	AM			
T	5	S	R	38	E
		S	35		
, -	S	3	S	2	
T	6	\mathbf{S}	R	38	E
		C	C		
		19	91		
	PI	S	120)6	

Description of corner evidence found:

Found large 8' dia. stone mound at ancient east-west-south fence intersection on rocky barren slope. Accepted this stone mound as the best available evidence of the original corner location.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner point as defined by the center of the found mound of stones, Set 1%" x 30" galv. iron pipe 18" into the ground, constructed 36" dia. stone mound around the monument. 2½" brass cap is marked as shown in the corner diagram.

From which, bearing objects:

A 5/8" dia. rebar bears N. 45° E., 25.0 feet A 5/8" dia. rebar bears S. 45° E., 25.0 feet

A 5/8" dia. rebar bears S. 45° W., 25.0 feet
A 5/8" dia. rebar bears N. 45° W., 25.0 feet
All rebars are set 0.1 feet above the ground with yellow plastic cap attached. Caps are marked "HANLEY ENGR. PLS 1206".

Set steel fence post 2' east from the corner monument. Attached USFS 54-9 sign to the fence post. Also attached 54-9 and 54-3 signs to bearing trees.

I certify that the above corner was properly monumented under my direct supervision on July 12, 1991, as witnessed by Larry McBroom and David Smith.

PROFESSIONAL. LAND SURVEYOR Office of ... County Surveyor County of ... Union amer D Hand OREGON SEPTEMBER 23, 1977 JAMES D. HANLEY Lysin To Blandin by SURVEYOR (COUNTY OFFICIAL) 1206

Form R6-7100-57 (9/71)

Date Filed 9

\$ GPO-798-276

REGISTERED