CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: None.

J-4DIAGRAM T6S R42E s 7 E1/16----S 18 1993 PLS 1106

See Survey 052-1994 Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At postion established by survey:

Set a $2\frac{1}{2}$ " X 30" aluminum pipe with a $2\frac{1}{2}$ " aluminum cap, 24" in ground and surrounded with a mound of earth and stone.

Attached sign 54-9 & 54-2 to steel fence post, set 4.0 feet West of monument. Set a steel fence post 4.0 feet South of monument.

New bearing trees established: A 11" douglas fir bears S 47° W - 18.2 feet, scribed: E1/16S18BT. A 16" douglas fir bears N 86° E - 8.1 feet, scribed: E1/16S7BT.

New bearing trees have a brass washer stamped 'PLS 1106' nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.

I hereby certify that the above corner monument was properly monumented to U.S.F.S standards by me on December 3, 1993.

Compass declination 18° East.

PROFESSIONAL LAND SHEVEYOR Will L. ares

OREGON JULY 22, 1977 WILLIAM R. WELLS

		renews 12-31-94	
	County of		
	ertify that the within instrument was filed	in this office	
for record on the day of	"Union county		
(COUNTY OFFICIAL)	SUBVER Od (DEPUTY)		
Form R6-7100-57 (9/71)	Data Paraived 11/3/84	*GPO-591-971, 1988	
	11/11/11		