Township 7 & 8 South   Range 41 East   Union County, Oregon.

CHAINS.	LKS.	
		The 1/8 corner on North Boundary N W 1/4 Sec 35 —
		Thence South
19	98	Set Stone 6 × 9 × 15 for 1/16 corner in center N W 1/4 Sec 35 —
39	96	The 1/16 corner in center W 1/4 Sec 35 —
59	94	Set Stone 6 × 10 × 15 for 1/16 corner in Center S W 1/4 Sec 35 —
		Thence East
19	79	Set Stone 6 × 9 × 14 for 1/16 corner in Cnter S 1/2 Sec 35 —
39	58	Set Stone 8 × 10 × 16 for 1/16 corner in Center S E 1/4 Sec 35 —
		The 1/4 Sec Corner bet Sec 2 & 3
		Thence East Through Sec 2
40	00	Set Temporary Center
60	00	Set Temporary 1/16 corner
79	40	Intersect East Bdy at 1/4 Sec Corner bet Sec 1 & 2
		Thence West
19	85	Set Stone 12 × 10 × 36 for 1/16 cor in Center E 1/2 Sec 2
39	70	Set Stone for Center Sec 2
		The Corner to Sec 1 = 2 = 35 & 36
		Thence South
40	53	The 1/4 Sec Corner bet Sec 1 & 2
		Thence South Var 20° E
20	00	Set Temporary 1/8 cor
40	08	The Corner to Sec 1 = 2 = 11 & 12
		Thence North
20	04	Set Stone 6 × 6 × 12 in for 1/8 cor
40	08	The 1/4 Sec cor bet Sec 1 & 2
		J W Fairweather deputy Co Surveyor