OREGON CORNER RESTORATION FORM

COUNTY: UNION DATE: 7/1/2016

CORNER DESIGNATION: P-21, 1/4 Section Corner common to Sections 23 & 24 Township 1 North, Range 38 East, W.M.

PREVIOUS RENEWALS/SURVEYS ETC:

Originally surveyed by Odell & Grey, Contract No. 120, dated May 27, 1867. His notes state "Set 1/4 section corner post, deposited marked stone and raised stone mound as per instructions."

MOUNUMENT AND ACCESSORIES FOUND:

No evidence found.

MOUNUMENT MARKING DETAIL:

HDJ T1N R38E S23| S24 1/4 6/2016

MOUNUMENT AND ACCESSORIES SET:

Per Survey No. 020-2016

Set a 2½" brass cap on 1½" x 30" iron pipe, 9" in ground and built 2.5' Wide X 1.75' Tall mound of stone at base of North, South and West fence corner from which I set

A 5/8" x 30" iron rod with yellow plastic cap Stamped "HDJ Design Group" bears N70°W 34.40'

A 5/8" x 30" iron rod with yellow plastic cap Stamped "HDJ Design Group" bears N53°E 44.80'

A 5/8" x 30" iron rod with yellow plastic cap Stamped "HDJ Design Group" bears S59°E 75.90'

A 5/8" x 30" iron rod with yellow plastic cap Stamped "HDJ Design Group" bears S41°W 47.75'

LOCATION AND COMMENTS:

Bearings taken with Silva hand compass and distances measured with a steel tape.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 696801.13	UNION COUNTY	
E = 8838538.26	SURVEYOR	
	Date Received 7/28/16	
COMPASS DECLINATION: 16° East	Date Filed 7/28/16	SURVEYORS' SEAL:
FIRM: HDJ Design Group 5 N. Colville, Suite 200 Walla Walla WA 99362	rie No. OJI OVIGIS	REGISTERED PROFESSIONAL LAND SURVEYOR
WITNESSES: Joseph R. Latimer Tim K. Bannister		OREGON JUNE 30, 1997 GREG E. FLOWERS 02820LS 7/25/24/6
	E C	ENEWS 12131/2017