
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

This corner was not established in the original survey.



No record of subsequent monumentation record found in the Union County Surveyor's records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Map of Survey Number 022-1997.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 2-1/2 inch by 30 inch aluminum pipe with aluminum cap marked

as shown, 28" in the ground.

From which:

A 5/8 inch by 30 inch rebar bears N 7° E, 6.65 feet, with aluminum cap marked BGB NE RP

A 5/8 inch by 30 inch rebar bears S 14° E, 7.75 feet, with aluminum cap marked BGB SE RP

I hereby certify that the above corner point was perpetuated as hereon described on July 23, 1997. Witnesses: Greg Blackman Jr. and Jeff Madsen

S 26
E 1/16
S 35
1997
OPLS 644

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON / JULY 10, 1964

DUANE I. GRIFFITH 644

Renewal Date July 30, 1999

I used a steel tape and magnetic compass in the establishment of new accessories. I used 18° east declination and the measurement was taken to the center of the aluminum cap on the rebar.

13 10 M COUNTY

13 10 M COUNTY

14 10 M COUNTY

15 10 M COUNTY

16 10 M COUNTY

17 10 M COUNTY

17 10 M COUNTY

18 10 M COUNTY

Page 15

V 20