
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

This corner was not established in the original survey.



No record of subsequent monumentation was found in the Union County Survey records. DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Map of Survey Number 022-1997. DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At a position determined by survey, I set 2-1/2 inch by 30 inch aluminum pipe with aluminum cap marked as shown, 36 inches in the ground, 6 inches below ground level.

From which, new B Os;

A 5/8" by 30" rebar bears N 46°E, 8.88 feet, with 1-1/2" aluminum cap marked "UCS NE RP".

A 5/8" by 30" rebar bears \$ 38° \mathbb{E}, 26.84 feet, with 1-1/2" aluminum cap marked "UCS SE RP".

A 5/8" by 30" rebar bears S 28°W, 25.00 feet, with 1-1/2" aluminum cap marked "UCS SW RP".

A 5/8" by 30" rebar bears N 68°W, 8.40 feet, with 1-1/2" aluminum cap marked "UCS NW RP".

Position is in a cultivated field 30± feet south of an east - west fence line.

I hereby certify that the above corner point was perpetuated as hereon described on July 7, 1997.

Witnessed by: Jeff Madsen Greg Blackman Jr.

OPLS 644 I used a steel tape and magnetic compass in the establishment of new accessories. I used 18° east declination and the measurement was taken to the

COUNTY

C 1/4

S 35

1997


TIN

04

SURVELOR

R 38 E





center of the aluminum cap on the rebar.

Page 7