## **CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

History of original corner establishment:

40.00 Set post for \( \frac{1}{4} \) Sec corner from which:

An Alder 6 in diam bears N 30° E, 21 lks dist An Alder 8 in diam bears N 40° W, 24 lks dist

DIAGRAM T1SR38E	
1/4	
S 8   S 9	
LS 2058	
1993	

## Description of corner evidence found:

Found 5/8" x 30" rebar with mutilated plastic cap 12" above ground at intersection of north - south fenceline and fence to east.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the exact location of the found rebar, Set a  $2\frac{1}{2}$  x 30" aluminum pipe with 3" cap 24" in the ground, from which:

A 9" fir bears N 73° E, 75.6 feet scribed \\$S9BT A 12" fir bears S 60° E, 65.2 feet scribed \\$S9BT A 12" fir bears S 11°50'W, 39.8 feet scribed \\$S8BT A 26" fir bears N 38° W, 19.1 feet scribed \\$S8BT

(COUNTY OFFICE	(AL)	(DEPLITY)	
	by		
for record on the day		. 19	
State of		•	strument was filed in this office
Office of	Cou	nty of	
THE NO. UTE 17771K			
File No. 092-1994R			
By Synt Bock	4		2058
1.			RONALD E STOLL
Date Filed 10/23/84			OREGON JULY 15 1983
Date Received 10/18/84			1017 0000 1019
			· MILL Still into
APRANSA CI E CALL			LAND SURVEYOR
SURVEYERS			PROFESSIONAL
	······································		REGISTERED