## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. U-25

History of original corner establishment: DIAGRAM None. T1S R40E R41E Description of corner evidence found: None. Description of monument and accessories I established to perpetuate the original location of this corner: Cap is marked: Corner set by proportioning. I set a  $2\frac{1}{3}$ "x30" aluminum capped aluminum pipe rising 10" in a mound of stones. T1S R40E S1/16S25 R41E Set steel fencepost 3 ft. North RLS1848 New BT's: 1986 A 6½" Doug. Fir bears N37½°W, 19.4 ft., blazed&scribed: S1/16S25BT An 18" Doug. Fir bears N81% W, 37.6 ft., blazed&scribed: S1/16S25BT Painted blazes and attached signs as per <u>Standard Specifications</u> <u>for Cadastral Surveys</u>, USFS Region 6, March 1982. A ¾" brass disk stamped "RLS 1848" was nailed to the lower ends of the blazes. 6200649 follows parallel to the east line of Sec 25, where it curves and goes East. Go West 300 ft. to fence and follow it South 300 ft. to the UNION COUNTY SURVEYOR corner, on South slope. REGISTERED Compass Declination: 19₺°E **PROFESSIONAL** Date Received 12-5-86 Witness: Jeremy Sutton LAND SURVEYOR I hereby certify that the above described corner monument and/or **OREGON** accessories were established as JULY 13, 1979 B. A. SUTTON 1 8 4 8 hereon described on Oct. 27, 1986. State of......, , I hereby certify that the within instrument was filed in this office for record on the...... day of...... , 19.....

..... by ......

Form R6-7100-57 (9/71)

(COUNTY OFFICIAL)

..........

(DEPUTY)

## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. U-25

History of original corner establishment:

None

T1S
R40E R41E
S1/16S25

Note:

This corner was previously established incorrectly in Survey of Record File No. 298-86R, recorded December 5, 1986. The monument described therein has been removed and placed as described below.

Description of corner evidence found:

Found a 2½" aluminum capped aluminum pipe marked: Found steel fence post 3 ft. north.

T1S R40E S1/16S25 R41E

> RLS1848 1986

From the corrected corner position, Bearing trees found:

A 6½" Doug Fir bears N37°W, 19.6 ft., blazed & scribed: S1/16S25BT An 18" Doug Fir bears N80¾°W, 37.6 ft., blazed & scribed: S1/16S25BT

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is stamped:

TIS

At the proportioned location, I set a 2½"X30" aluminum capped aluminum pipe rising 10", in a mound of stones. Set a steel fence post 3 ft. north of corner.

R40E S1/16S25 R41E

> RLS1848 1988

Used existing BT's:

A 63" Doug Fir bears N37°W, 19.6 ft., blazed & scribed: S1/16S25BT An 18" Doug Fir bears N80%°W, 37.6 ft., blazed & scribed: S1/16S25BT

Painted blazes and attached signs as required in <u>Specifications for Cadastral Surveys</u>, USFS Region 6, March, 1982. A ½" brass disk stamped "RLS1848" is nailed to lower end of blazes between the B & T.

6200649 follows parallel to the east line of Sec 25, where it curves and goes East. Go West 200 ft. to fence and follow it South 300 ft. to the corner, on South slope.

Compass Declination: 195°E Witness: Jeremy Sutton

I hereby certify that the above described corner monument and/or accessories was perpetuated as hereon described on May 14, 1988. REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 13, 1979
B. A. SUTTON
1 8 4 8

UNION COUNTY SURVEYOR

Dato Received 6-20-88

Data Filed 6-28-88

By G. LANGUEZ DORM

File No. 82-88R

Office of	County of
State of / here	by certify that the within instrument was filed in this office
for record on the day of	, 19
***************************************	by
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

☆ GPO---798-276