CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

None.

T 1 S R 40 E V-10

DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 016-2019

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE LOCATION OF THIS CORNER:

At position determined by survey I set a 5/8" x 30" iron pin, 31" in the ground and 1" below the road surface, with 2 ½" aluminum cap marked as shown below, from which:

NEW BEARING OBJECTS:

A 16" Tamarack bears South 16° East a dist. of 7.80 ft., marked W 1/16 S33 BT. A 14" Tamarack bears North 12° West a dist. of 11.20 ft., marked W 1/16 S28 BT.

East and South bearing fence corner falls on SE BT.

Monument falls in East/West forest road.


I hereby certify that the corner was monumented on July 8, 2019.


Witness: Kyle A. Tucker

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2021





I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.