CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. C-03

History of original corner establishment:
NONE

DIAGRAM

T1S R41E

C3.56

Description of corner evidence found: None

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is stamped:

Set 2½" Brass cap in concrete 6" below the road surface. Two 60d spikes are imbedded in the concrete to provide iron for a magnetic locator. Set steel fence post 20 ft. east of corner on steep cutbank.

T1S R41E C4•S6 RLS1848 1986

New BT's:

A 9½" Doug Fir bears S54¾°W, 48.5 ft., blazed&scribed C¼S6BT

A 10" Doug Fir bears S37%°E, 150.3 ft., blazed&scribed: C%S6BT

Painted blazes and attached signs as required in <u>Specifications for Cadastral Surveys</u>, <u>USFS</u> Region 6, March, 1982. A ¾" brass disk stamped "LS1848 nailed to lower end of blazes. To find corner take Rd. 6200600 1 mile South from 6200, corner is buried in the center of the road.

Compass Declination: 19½°E
Witness: Jeremy Sutton
I hereby certify that the above
described corner monument and/or
accessories was perpetuated as
hereon described on Oct. 20, 1986.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 13, 1979
B. A. SUTTON
1 8 4 8

ZOKARIOK
Date Received 11-21-86
Date Filed 11-26-86
By G. LANGUE DEAM

File No. 272-86 R

UNION COUNTY

Office of	
	ereby certify that the within instrument was filed in this office
for record on the day of	
	by
(COUNTY OFFICIAL)	(DEPLITY)

Form R6-7100-57 (9/71)

\$U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Note:

This corner was previously established incorrectly in Survey of Record File No. 272-86R, recorded November 26, 1986. The monument described therein has been removed and placed as described below.

Index File No. C-03

DIAGRAM

TlS R41E

C1/4 • S6

Description of corner evidence found:

From the corrected corner position, Bearing trees found:

9.5" Douglas Fir bears S54 3/4°W, 48.5 ft., blazed & scribed: Cl/4S6BT. 10" Douglas Fir bears S37 1/4°E, 150.3 ft., blazed & scribed: Cl/4S6BT.

2 1/2" brass cap is set in concrete 6" below the road surface. Cap is stamped: TIS R41E

C1/4 • S6

RLS 1848 1986

Steel fencepost found 3.5 ft. west of corner.

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is stamped: TlS R41E

C1/4 S6

Corner set by intersection. Set 2.5" brass cap in concrete 16" below surface on steep cut slope on east side of road. Imbedded a 3 1/2" ceramic

RLS 1848 1987

on east side of road. Imbedded a 3 1/2" ceramic magnet in concrete under the cap to provide magnetic attraction for metal detectors.

Used same BT's. Monument in center of road, set in error, was stamped and used as a reference monument. Cap is now marked: T1S R41E

Painted blazes and attached signs as required in Specifications for Cadastral Surveys, USFS Region 6, March 1982.

C1/4 S6 RM N89°27'E 23.00 ft. RLS 1848 1987

Corner is on a steep westerly-sloping cutbank of Road 6200600 one mile south of 6200.

Compass Declination: 19 1/2°E Witness: Jeremy Sutton

I hereby certify that the above described corner monument and/or accessories was established as hereon described on August 13, 1987.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 13, 1979
B. A. SUTTON
1 8 4 8

Date Filed 1-26-88

UNION COUNTY

File No. 57-88 R

Office of	County of	
State of	ate of , / hereby certify that the within instrument was filed in this offi	
for record on the day o	of , 19	
	by	
(COUNTY OFFIC		