CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 2 N R 39 E N-20

 S	23	

DESCRIPTION OF CORNER EVIDENCE FOUND:

SEE SURVEY NUMBER CS 010-2018

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a $5/8" \times 30"$ iron pin, 26 inches in the ground, with 2' collar of stone, from which:

NEW BEARING OBJECTS: An 8" Ponderosa Pine bears South 27° East, a distance of 18.10 feet, marked E1/16 S23 BT. A 9" Ponderosa Pine bears North 53° West, a distance of 49.90 feet, marked E1/16 S14 BT.


Falls in remnants of East and West running barb wire fence.


I hereby certify that this monument was set March 28, 2018. Corner falls approx. 300 feet North of Kingsbury Rd. Set a steel fencepost approx. 1 ft. North of corner monument

Witness: Kyle Tucker



Renewal Date: June 30, 2019





I use a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 15° East. Distances are to a spike in the root crown of the trees. Bearings are to a brass washer in the lower blaze marked OPLS 83571.