History of original corner establishment:

Corner not previously set

T-7	
DIAGRAM	
T 2N	R 39 E
C 1/4	S 29
	đ
	:

Description of corner evidence found:

Corner not previously set


See map of survey number 1+81 as recorded in the office of the Union County surveyor.

Description of monument and accessories I established to perpetuate the

original location of this corner: At the intersection of the line between the east and west $\frac{1}{4}$ section corners and the line between the North and South $\frac{1}{4}$ section corners all in section 29, I set a 1" by 30 " galvanized iron pipe with brass cap marked as shown, 28 inches in the ground; from which B.T.s;

A 14 inch Tamarack bears S 14° W , 26.9 feet, Marked C $\frac{1}{4}$ S 29 BT

A 20 inch Red Fir Bears N 27° W, 7.8 feet, marked C4 S 29 BT



I used a steel tape and magnetic compass with 20° declination East declination. I set a brass washer marked OPLS 991 at the BT blaze.

Office of	the within instrument was filed in this office CHINA
by	
(COUNTY OFFICIAL)	(DEPUTY) Date Received
Form R6-7100-57 (9/71)	Date Filed
	Ву
	File No. 291-83R