


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. Y-16

History of original corner establishment:

None.



Description of corner evidence found:

None.

Corner falls on bottom of small drain about 125' west of road.

Description of monument and accessories established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" X 30" galvanized pipe and brass cap marked: Set pipe 24" in the ground and mound of stone around to cap.

From which by magnetic declination of N20°E:

A 15" fir bears N66°E, 70.6 ft. scribed SE1/16S34 BT. A 10" fir bears S16°E, 44.9ft. scribed SE1/16S34 BT. Painted blazes red and 6" red band around. Placed 54-3s, 54-9s and brass washers stamped PLS 1051 on BTs. Placed 54-2 and 54-9 on steel fence post 5' south and 54-2 on steel fence post 5' west of the corner.

T2S R34E
SE
1/16 S34
OR PLS 1051
1980

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel Rowland
Doug Moser
Ron Gilroy

November 3, 1980

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Barry B. Barbour
OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of... County Surveyor's County of... Union
State of... Oregon I hereby certify that the within instrument was filed in this office
for record on the 30th day of... January....., 19.81

(COUNTY OFFICIAL)

(DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received _____

★ GPO—798-276

Date Filed _____

By _____

File No. 197-84R