USDA-FOREST SERVICE GPO 9	40-117		
Index ' File No. <u>N 1</u>	CORNER RECORD	(SEARCH) Tract or	
T 2S R.35E	R.D. <u>La Grande</u>	151.4) Survey N	o No
Merid. Will	N. F. WW	State Oregon	
CORNER DIAGRAM	DESCRIBE CORNER MONUME		
18	none	·	
ï *	DESCRIBE BEARING TREES OR	OTHER OFFICIAL ACCESSO	2 PIES FOUND
PHOTO IDENTIFICATION DATA Photo No. UBM o 8C 35 Filed At.	Sec 24 BT 16" WL of Sec 19 BT 14" WL of Sec 13 BT 16" WL	lown	
Object Ident	DESCRIBE CORNER LOCATION	PELATIVE TO NEAD-BY CEAT	TURES, ALSO HOW TO REACH CORNER
ldent. By <u>JC Davidson</u> Signature	To get to corner turn	n off S-214 and fold	low sign to Bowman Spring ring proceed. West about 14
PLANE COORDINATE POSITION DATA	miles. There is a sec	tion board marker i	for the 4 corner to section
StateZone	. 19 along this road an	d an old building a	about 2/3 mile before you
X	get to corner.	J	,,
Estab. By			
Signature	Title Division	Headquarters	Date 7100 52 (2.00)
J C Davidson	Forester Whitman	La Grande	7100-52 (3/68) 10/25/65

	UNION COUNTY SURVEYOR		
)ate Received		
2	Date Filed .		
	Y		
	ile No. 48-87R		