## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishmen	History	of	original	corner	estab	lishmen
---	---------	----	----------	--------	-------	---------

Corner established by Jacob C. Cooper under GLO contract no. 397 dated July 1, 1881.

Surveyor General records state:

Set post  $4\frac{1}{2}$  ft long 4 ins square 24 ins in the ground in dense forest of pine and fir timber on W. side of mountain 200 ft below the summit for cor to secs 1, 2, 35 and 36 marked T 1 S S 36 on NE, R 37 E S 1 on SE, T 2 S S 2 on SW and S 35 on the NW faces with 1 notch on the E. and 5 notches on the W. edges from which

DIAGRAM T 1 S R 37 E						
S 35	S 36					
S 2	S 1					

A fir 24 ins diam bears N 63° E 39 1ks dist marked T 1 S R 37 E S 36 BT. A fir 24 ins diam bears N 20° W 20 1ks dist marked T 1 S R 37 E S 35 BT. A fir 24 ins diam bears S 74° W 34 1ks dist marked T 2 S R 37 E S 2 BT. A fir 24 ins diam bears S 74° E 21 1ks dist marked T 2 S R 37 E S 1 BT. Description of corner evidence found:

Found a fir 36 ins diam for Section 2 bearing tree with healed blazes.

Found a root hole for Sections 1 and 35 bearing trees.

Did not find original wood post or Section 36 bearing tree.

## Description of monument and accessories I established to perpetuate the original location of this corner:

Set a  $2\frac{1}{2}$  inch aluminum cap on a 2 inch aluminum pipe 30 inches long 26 inches in the ground with 4 inches projecting out of the ground with a surrounding earthen mound. (No rock available within limits.) Set a 6 foot steel fence post alongside with a sign 54-4 attached.

Aluminum cap marked thus:

T 1 S R 37 E T 2 S 1983

ORLS 1639

New bearing trees:

A tamarack 18 ins diam bears S 28° E, 40.3 feet dist marked T 2 S R 37 E S 1 BT A tamarack 10 ins diam bears N 43° E, 24.4 feet dist marked T 1 S R 37 E S 36 BT A tamarack 9 ins diam bears N 14° W, 45.0 feet dist marked T 1 S R 37 E S 35 BT

Each new bearing tree has a sign 54-3 attached below a 6 inch band of red paint and a brass washer marked PLS 1639 nailed flush with BT blaze. A sign 54-4 is attached on

opposite side of tree from BT blaze.

I hereby certify that the above described corner was properly monumented by me of Sept. 7, 1983, and witnessed by Jim DeMastus.

REGISTERED **PROFESSIONAL** LAND SURVEYOR

William L. Hanley

State of...Oregon........., I hereby certify that the within instrument was filed in this office for record on the...... day of...... , 19..... ..... by ..... UNION COUNTY COUNTY OFFICIAL

OREGON JULY 14, 1978 WILLIAM L. HANLEY 1639

(DEPUTY)

SURVEYOR

Form R6-7100-57 (9/71)