-2-	UNION COUNTY SURVEYOR
CORNER 35 and 36	3000000
ORIGINAL:	Date Received
Stone (found disturbed at fence corner) I used fence corner post	Date Filed
	84
SECTION CORNER 25, 26, 35, & 36	File No. 312-84R
ORIGINAL:	1.
Stone (found in place) 24" Fir N65°W 56 LKS (not found)	
12" Fir S20°W 42 LKS (now 28" "R36ES35" visible)	
10" Fir S10°E 49 LKS (not found) 15" Fir N40°E 49 LKS (not found)	UNION COUNTY SURVEYOR
RESTORED:	
	Date Received
Set 4" x 4" x 48" White post near stone 19" Fir S34°E 52.8 ft. scribed, "T2SR36ES36BTRS691"	Date Filed
8" Fir N81°W 60.7 At. scribed, "T2SR36ES26BT"	Ву
12" Fir N57°E 34.3 ft. scribed, °T2SR36ES25BT"	File No. 313-84 R
Witnessed by: J. Hollingsworth A. Slack	File No. 313 84 85
R. Hemmer T. Stose	
SECTION CORNER 25, 30, 31 & 36	
ORIGINAL:	1
	T25 R37E)
10" Fir N42°W 20 LKS (now down, scribe visible) 10" Pine N5°E 28 LKS (now 20")	UNION COUNTY SURVEYOR
24" Pine S2°E 8 LKS (now rotted stump)	30
RESTORED:	Date Received
Set 5/8" x 30" iron pin 15" in ground.	Date Filed
Erected mound of stone around pin.	
9" Fir N732°W 46.7 ft. scribed, "T2SR36ES25BT" 15" Fir S8°W 38.8 ft. scribed, "T2SR36ES36BT"	Ву
15" Fir S52°E 31.2 ft. scribed, "T2SR37ES31BT" Yellow corner tag on SW BT.	File No. 314 - 84 R
Witnessed by: A. Slack By: J.E. Hounsswort	
T. Stose FOR: G. LANGLITZ, DEP.	Co. Suevenore.
CORNER 36 and 31	
ORIGINAL	
Post (not found)	
10" Pine N23°E 55 LKS (not found)	
10" Pine S30°W 58 LKS (now 23", scribe visible)	UNION COUNTY SURVEYOR
Dai	e Received
Da	te Filed
Ву	
File	No. 315-84-R

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by General Land Office contract survey;

The original notes state; A stone 18x15x8 inches from which; (marked with one notch on south and 5 notines on north edge) A fir 10" in diam bears N42°W 20 lks dist marked T23 S25BT; A pine 10" in diam bears N5°E 28 lke dist marked R37E 330BT; A pine 24" in diam bears 52° 8 8 lks dist marked 723 R31BT;

V-1		
DIAGRAM25		
R 36E	R37EWM	
32 5	330 331	
536	531	

Description of corner evidence found:

In section 25, found down log with scribe.

In section 30, found 18" pine anag with scribe. In section 31, found stump with scribe.

UNION COUNTY **SURVEYOR** Date Received Date Filed 319-84R

COR

ORE LIC 381 1970

R375

Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a 30° galvanised pipe with an eight inch plate welded to bottom and a bronse eap on top. The hele was back filled with stone and tamped soil.

I stamped the disk

From the monument the original bearing trees were (none) I established the fellowing new bearing trees; Fir 8" in diam bears M62"W at a dist of 49.6 ft. and scribed 728 R36E 52587; Yellow pine 17° in diam bears #3°E at a dist of \$2.0 ft. and

Red fir 19" in whem bears 545°E at a dist of 32.1 ft. and seribed T25 RY7E \$3187;

Red fir 16" in diam bears 39" at a dist of 39.7ft. and seribed T2S R36E S36ET; The distance measured to center of respective trees on level. I placed bearing tree signs on both old and new bearing trees and painted stripe around trees. I placed a steel fence post with USFS sign 54-4 attached near the corner and placed USFS boundary sign on steel post indicating USFS land to north.

Office ofCounty Surveyor	. County of	Union
State of Oragon I hereby certify	that the within income	mana uma filad ia aki 10
for record on the 23 day of July JAMES G. Yoels (COUNTY OFFICIAL)		4 p'clock P m. (signed)
James G. Voels	by armed	Mack,
(COUNTY OFFICIAL)	15	PERMI)

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by John A. Hurlburt under GLO contract no. 201 dated August 5, 1873.

Surveyor General records state:

Set basalt stone $18 \times 15 \times 8$ - 10 ins in ground for cor to sec 30-31-25 and 36

Fir 10 in dia N 42° W 20 1ks Pine 10 in dia N 5° E 28 1ks Pine 24 in dia S 2° E 8 1ks No other near

DIAGRAM	
	2 S R 37 E S 30
S 36	S 31

Description of corner evidence found:

A pine snag 28 ins diam with partially healed blaze and burned face, no scribes identified, for Section 30 original bearing tree.

A rotten stump with BT scribes on loose piece of tree for Section 31 original BT.

A down and rotting log with burned blaze, no scribes, for Section 25 original BT.

This corner was remonumented by PLS 381 in 1970 with a $3\frac{1}{2}$ inch brass cap on a 2 inch iron pipe from which the following bearing trees were established:

A fir 8 ins diam bears N 62° W, 49.6 ft dist marked T 2 S R 36 E S 25 BT A pine 17 ins diam bears N 03° E, 42.0 ft dist marked T 2 S R 37 E S 30 BT A fir 13 ins diam bears S 45° E, 32.1 ft dist marked T 2 S R 37 E S 31 BT A fir 16 ins diam bears S 13° W, 39.7 ft dist marked T 2 S R 36 E S 36 BT

All of these trees were found to be in good condition and growing vigorously.

Description of monument and accessories I established to perpetuate the original location of this corner:

Improved surrounding rock mound around existing corner monument and attached sign 54-4 to 6 foot steel fence post alongside.

Existing brass cap marked thus:

To existing bearing trees established by PLS 381 placed sign 54-3 below a 6 inch band of red paint and attached sign 54-4 to opposite side of tree from BT blaze.

To remains of original bearing trees painted 6 inch band of red paint around and attached signs 54-3 and 54-4.

I hereby certify that the above described corner monument was properly maintained to Forest Service standards by me on Nov. 7, 1983, and witnessed by Jim DeMastus.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William L. Hanley
OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Form R6-7100-57 (9/71)

SURVEYOR

UNION COUNTY

Date Filed 11-14-83

BY G. LANGLITZ DEPUTY

File No. 387- 83