


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

A-2

(T2S R38E)




History of original corner establishment:
 Corner established by T. Davenport under GLO contract no. 102 dated July 20, 1863.

Surveyor General records state:
 Set post corner to Secs 5, 6, 31 & 32 from which,
 A pine 7 ins diam bears N 50° E, 97 lks dist
 A pine 6 ins diam bears S 75° E, 161 lks dist

Description of corner evidence found:
 Original post corner not found.
 Original bearing trees found, opened by others.
 A pine stump 12 ins diam for Section 5 bearing tree..negative of scribes found, original scribes removed by others.
 A pine snag 23 ins diam for Section 32 bearing tree..previously opened by others with chain saw..typical blaze and overgrowth marks, no scribes observed.
 This corner was remonumented by PLS 644 in 1978 with a 2½ inch brass cap on a 2 inch iron pipe projecting 8 inches out of the ground with a surrounding rock mound. See Union County survey no. 73-78.

Bearing trees established by PLS 644:
 A fir 15 ins diam bears S 73° E, 55.7 ft dist marked T 2 S R 38 E S 5 BT with 1 inch overgrowth, condition good, growth vigorous.
 A tamarack 13 ins diam bears N 55° E, 77.5 ft dist marked T 1 S R 38 E S 32 BT with 1 inch overgrowth, condition good, growth vigorous.
 Description of monument and accessories established to perpetuate the original location of this corner:

Existing brass cap monument established by PLS 644 marked thus:



Improved surrounding rock mound around monument and placed a 6 foot steel fence post alongside with a sign 54-4 attached.

New bearing trees established:
 A spruce 7 ins diam bears S 14° W, 70.0 ft dist marked T 2 S R 38 E S 6 BT
 A fir 14 ins diam bears N 12° W, 127.2 ft dist marked T 1 S R 38 E S 31 BT
 Each new bearing tree has a sign 54-3 attached below a 6 inch band of red paint and has a brass washer marked PLS 1639 nailed flush with BT blaze. A sign 54-4 is attached on the opposite side of tree from BT blaze.
 To the bearing trees established by PLS 644, attached a sign 54-4 to opposite side of tree from BT blaze and painted a 6 inch band of red paint around.

I hereby certify that the above described corner monument was maintained to Forest Service standards by me on Oct. 11, 1983.

REGISTERED PROFESSIONAL LAND SURVEYOR

William L. Hanley

OREGON
 JULY 14, 1978
 WILLIAM L. HANLEY
 1639

Office of..... County Surveyor County of..... Union
 State of..... Oregon I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Received 11-16-83
REG-798-276

Filed 11-18-83

By G. LANGLITZ, DEPUTY

File No. 406-83 R