# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

marked 1/4 S. BT.

In July 1882, under GLO Contract No. 450, Henry Meldrum set post 3 feet long, 3 ins. square, 24 ins. in ground for 1/4 Sec. Cor. marked 1/4 S on N face from which:

A Fir 30 ins. dia. bears N58°W, 40 lks. dist. marked 1/4 S BT. A Fir 20 ins. dia. bears S48°E 50 lks, dist.

Index	File	No.	J-11	
DIAGRAM				
T	<b>2S</b> .	R40E		
<u>1</u> -	\$9 \$16	<del></del>		

Description of corner evidence found:

A diligent search and no evidence of the original post or BT's could be found

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point established midway on line between the Section Corners to the east and west set  $2\,1/2"x30"$  galvanized pipe with brass cap stamped: S 186

Set pipe 22" in ground with mound of stone to cap.

Bearing trees:


A Tamarack 9" dia. bears N 6° W, 30.5 ft., scribed 1/4 S9 BT

A Tamarack 8" dia. bears S82°E, 32.1 ft. scribed 1/4 S16 BT

Attached 54-3 & 54-4 signs to both BT's and brass washer stamped LS 1294 to foot blaze of both BT's. Painted blazes & 6" band around both BT's red. Attached 54-2 and 54-4 signs to metal post 5 ft. east of corner.

I hereby certify the above coner monument was reestablished as herein described September 14, 1981.

> Witnesses: R. Orton G. Orton



**T2S R40E** 

**S9** 

**S16** 

1981

OR PLS 1294

County Surveyor Union Howard L. Perry (COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

Date Received ₩ GPO--798-276 Date Filed file No.\_

UNION COUNTY

SURVEYOR

## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

· History of original corner establishment:

Refer to Union County Remonumentation Record No. 335-84R and Union County Survey No. 74-81 for original corner information and for 1981 establishment of corner position.

DIA	GRAM	1	
1/4	2S 	R40E <u>9</u> .6	

Description of corner evidence found:

Found the 1981 monument as previously described.

Refer to survey recorded during September, 1989 which revises Survey 74-81.

Description of monument and accessories I established to perpetuate the original location of this corner:

Found and removed the monument established by Survey 74-81 and reset it at the revised position:

Reset a 2"x30" galvanized iron pipe 28" in the ground with brass cap marked:

T2S R40E <u>S9</u> S16 1981

(Note additional markings placed on brass cap)

Reset 1989 OR PLS 1294

FROM WHICH:

The 1981 NE BT, a 10" Western Larch, now dead and down, marked as previously described, bears approximately N 10° E 25 feet.

The 1981 SE BT, an 8" Western Larch, now dead, marked as previously described, bears 5 68° E 33.7 feet.

## **NEW BEARING TREES:**

A 12" White Fir, scribed "1/4 S9 BT" on a double blaze, bears east 50.3 feet.

A 10" Douglas Fir, scribed "1/4 S16 BT" on a double blaze, bears S 15° E 61.2 feet.

Attached brass washer marked "LS 1294" to BT blaze on each new BT.

Magnetic compass (18-1/2° E. declination). Steel Tape.

September 6, 1989

I hereby certify that the survey activities described on this record were performed under my direct supervision.

Gary L. Langlitz, LS 1099 David Siderius

Office of...... County of.....

State of....... I hereby certify that the within instrument was filed in this office

for record on the...... day of..............................., 19..... ..... by ...... (COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR

PERRY

REGISTERED

**PROFESSIONAL** 

OREGON L

HOWARD L.

Date Received 9-18-89

Date Filed\_

#### CERTIFIED RECORD OF LAND CORNER MONUMENTATION

#### HISTORY OF ORIGINAL CORNER ESTABLISHED:


Corner originally established by Henry Meldrum in GLO contract number 450, dated June 11, 1882. Surveyor General field notes state:

Set post 3 ft. long, 3 ins. square 24 in. in ground for 1/4 Sec. Cor marked 1/4 S on N face, from which:

A Fir 30 in. diam. bears N58°W, 40 lks. dist. marked 1/4 S BT.

A Fir 20 in. diam. bears S48°E, 50 lks. dist. marked 1/4~S BT.

Corner not found by Howard Perry in Survey 74-81 and set at proportionate position. Corner reset in Survey Number 15-89 by Howard Perry. Union County Monumentation record 169-89R states:



Reset a 2"x30" galvanized iron pipe 28" in the ground with brass cap, from which: NEW BEARING TREES:

A 12" White Fir, scribed "1/4 S9 BT" on a double blaze, bears East 50.3 feet. A 10" Douglas Fir, scribed "1/4 S16 BT" on a double blaze, bears S15°E, 61.2 feet.

#### DESCRIPTION OF CORNER EVIDENCE FOUND:

Found a  $2 \ \frak{l}''$  iron pipe with  $2 \ \frak{l}''$  brass cap marked as shown below, 2 inches above ground, from which:

A 22 inch White Fir bears East, a distance of 50.3 feet, alive and vigorous with healed blaze.

A 24 inch Douglas Fir bears South  $15^{\circ}$  East, a distance of 61.2 feet, alive and vigorous with healed blaze.

SEE SURVEY NUMBER 014-2016

## DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED


#### TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

From the iron pipe position:

## NEW BEARING OBJECTS:

An 8 inch Ponderosa Pine bears South 53° West, a distance of 36.20 feet, marked 1/4 S16 BT. A 10 inch Western Larch bears North 19° West, a distance of 10.85 feet, marked 1/4 S9 BT.


I hereby certify that the corner was perpetuated April 25, 2016.



REGISTERED
PROFESSIONAL
AND SURVEYOR

JEFFREY S. HSU 83571

Renewal Date: June 30, 2017



I used a steel tape and magnetic compass to establish the corner accessories. Magnetic declination used was  $15^{\circ}$  East. Distances are measured to a 60d spike in the right hand side of the root crown of the new bearing trees.