CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In July 1882, under GLO Contract No. 450, Henry Meldrum set a post 3 ft. long, 3 ins. square, 24 ins. in ground for 1/4 Sec. corner marked 1/4 S on N Face from which;

A Fir 20 in. diam. bears N19°E., 25 lks. dist. marked 1/4 S. B.T.

A Fir 24 in. diam. bears S20°W, 19 lks. dist. marked 1/4 S. B.T.

Index File No. J-15

Description of corner evidence found:

A diligent search was made and no evidence of the original post or BT's could be found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Therefore at the halfway point on line between the section corners to the east and west set 2 1/2"x30" galvanized pipe with brass cap stamped:

Set pipe 24" in ground with mound of stone to cap.

Bearing trees:

A White Fir 10" dia. bears N67°E, 15.6 ft. scribed 1/4 S10 BT

A Lodgepole Pine 8" dia. bears S60°W, 41.5 ft. scribed 1/4 S15 BT

Attached 54-3 & 54-4 signs to both BT's and brass washer stamped LS1294 to foot blaze of both BT's. Painted blazes and 6" band around both BT's red.
Attached 54-4 sign to metal post 6 ft. west of corner.

I hereby certify the above corner monument was reestablished as herein described on September 11, 1981.

Witnesses:

R. Orton

G. Orton

REGISTERED
PROFESSIONAL'
LAND SURVEYOR

OREGÓN
SEPTEMBER 29, 1977
HOWARD L. PERRY,
1 2 9 4

File No. 338-84R

T2S

R40F

S15

1981

OR PLS 1294

County Surveyor Office of	Union	
State of. Oregon , I hereby certify that the top of record on the 26. day of October Howard L. Penry by (County Official)	within instrument was filed in t	UNION COUNTY SURVEYOR
Form R6-7100-57 (9/71)		Date Filed

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

· History of original corner establishment:

Refer to Union County Remonumentation Record No. 338-84R and Union County Survey No. 74-81 for original corner information and for 1981 establishment of corner position.

DIAGI	RAM	
T2S	R40E	
1/4 -	10 15	·

Description of corner evidence found:

Found the 1981 monument as previously described.

Refer to survey recorded during September, 1989 which revises Survey 74-81.

Description of monument and accessories I established to perpetuate the original location of this corner:

Found and removed the monument established by Survey 74-81 and reset it at the revised position:

Reset a 2"x30" galvanized iron pipe, 26" in the ground, with brass cap marked:

T2S R40E <u>S10</u> S15

(Note additional markings placed on brass cap)

1981 Reset 1989

FROM WHICH:

OR PLS 1294 The 1981 NE BT, a 10" White Fir, alive and in good condition, marked as previously described, bears East 14.2 feet.

The 1981 SW BT, an 8" Lodgepole Pine, is now a dead broken stub, approximately 4' tall, marked as previously described, bears S 53° W 44.8 feet.

NEW BEARING TREES:

An 8" White Fir, scribed "1/4 S15 BT" on a double blaze, bears S 15° E 27.4 feet. Attached brass washer marked "LS 1294" to BT blaze of new bearing tree.

Magnetic compass (18-1/2° E. Declination). Steel Tape.

September 1, 1989

I hereby certify that the survey activities described on this record were performed under my direct supervision.

Gary L. Langlitz, LS 1099 David Siderius

REGISTERED **PROFESSIONAL** AND SURVEYOR OREGON

AWOH	RD 18	Ļ.	PERR 4	

Office of			
Office of	ntv of		
State or / hereby certify that the	within instrument was filed in this of	·····	**************************************
for record on the day of	. , 19	UNION	COUNTY
(COUNTY OFFICIAL)	/DEBUTY	JUK.	VEYOR

Form R6-7100-57 (9/71)

Date Received 9-18-89 ☆ GPO 799-509 Dato Filed