


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

L-25

History of original corner establishment:



Corner originally ESTABLISHED by Henry Meldrum under GLO contract No.450 and dated June 11,1882. Surveyor General records state: Set post 3 ft long 3 in square 24 in in ground for 1/4 Sec Cor marked 1/4S on W face, from which: A pine 7 in diam bears N10°E, 25 lks dist marked 1/4S BT. A pine 10 in diam bears N28°W, 25 lks dist marked 1/4S BT.

Corner REESTABLISHED by Alonzo Gesner under GLO contract No.683, dated June 7 1898, during his resurvey of the east boundary of T.2S.,R.40E.,W.M... The 1/4 Sec Cor post destroyed. I re-established the Cor as follows, set fir post 4 ft long 4 in Square 24 ins in ground marked 1/4S on W face from which: A pine 8 in diam brs S28°W, 25 lks dist marked 1/4S BT. Agreeing with statements of the U.S.Surveyor General & the other bearing tree had been destroyed I marked a tamarack 18 ins diam bears N40°E, 50 lks dist marked 1/4S BT.

Description of corner evidence found:

Searched 6 man-hours total on 7-22-88, 8-4-88 & 8-19-88 in logged off area - corner or accessories not found and corner declared lost.

UNION COUNTY SURVEYOR	
Date Received	<u>6-8-89</u>
Date Filed	<u>6-9-89</u>
By	<u>G. LANGLITZ DEPUTY</u>
File No.	<u>115-89 R</u>

Description of monument and accessories I established to perpetuate the original location of this corner:

At proportioned position on line between NE and SE corners to Section 13...

Set 2 1/2" aluminum cap on 2"x 30" aluminum pipe 20" in ground to bedrock & surrounded with mound of earth & stone. Set 6' steel fence post alongside corner with sign 54-9 attached. Cap marked as shown in corner diagram.

New bearing trees established:

A white fir 21" diam brs S49°W, 56.2' dist mkd 1/4S13 BT.
A red fir 25" diam brs N41°W, 91.2' dist mkd 1/4S13 BT.

New bearing trees have a brass washer stamped PLS 1639 nailed to face of blaze. Attached signs 54-3 & 54-9 and painted face of blaze and 6" band of red around each BT.

Compass declination 19° East.

I hereby certify that the above corner monument was properly REESTABLISHED to U.S.F.S. standards by me on August 19, 1988 and witnessed by Jim DeMastus.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William D. Hanley

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of.....County Surveyor..... County of..... Union.....
State of..... Oregon..... I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)