# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

### History of original corner establishment:

Corner established by Henry Meldrum under GLO contract No. 450 and dated June 11, 1882.

Surveyor General records state:

Basalt stone 18 x 10 x 7 ins, 12 ins in ground for Cor to Secs 13, 14, 23 & 24, marked with 3 notches on S and 1 on E edge on top of hill from which: A pine 26" dia brs N12 $^{\rm O}$ W, 66 lks dist mkd R40ES14 BT. A pine 15" dia brs S51 $^{\rm O}$ W, 86 lks dist mkd S23 BT. A pine 26" dia brs S56 $^{\rm O}$ E, 86 lks dist mkd S24 BT. A pine 6" dia brs N07 $^{\rm O}$ E, 62 lks dist mkd T2SS13 BT.

N-21	
DIAGRAM	
T 2 S	R 40 E
S 14	s 13
S 23	S 24
19	87
ORLS	1639

## Description of corner evidence found:

A stone 20 x 10 x 7"(record, 18 x 10 x 7") in place on surface marked with 3 notches on the S face and 5 notches on the W face (record, 1 notch on E face) from which:

Rotten pine log 24" dia brs  $S51^{O}W$ ,66 lks dist per record, no marks identified. Rotten pine log 24" dia brs  $S51^{O}W$ , 86 lks dist per record, no marks. Pine log 20" dia brs  $S56^{O}E$ ,86 lks dist per record with "S24 BT" scribes visible in chopped open double blaze. No trace of section 13 BT.

# Description of monument and accessories I established to perpetuate the original location of this corner:

At position of found stone...

Set  $2\frac{1}{2}$ " aluminum cap on 2" aluminum pipe 25" in ground & 5" projecting out of ground with surrounding rock mound & 6' fence post alongside with sign 54-9 attached. Cap marked as shown in corner diagram. Buried stone alongside.

New bearing trees established: A 18" IP pine brs N48°E, 45.1' mkd T2SR40ES13 BT. A 18" IP pine brs S25°E, 52.0' mkd T2SR40ES24 BT. A 15" IP pine brs S42°W, 45.0' mkd T2SR40ES23 BT. A 15" IP pine brs N49°W, 36.3' mkd T2SR40ES14 BT.

New BT's have a brass washer stamped PLS 1639 nailed to face of blaze. Attached signs 54-3 & 54-9 and painted face of blaze and 6" band of red around each BT. Set 6' steel fence post alongside of corner and attached sign 54-9.

Compass declination 17° East.

I hereby certify that the above described corner monument was properly remonumented by me and witnessed by Jim DeMastus on August 10, 1987. In Dellatter

REGISTERED PROFESSIONAL LAND SURVEYOR

William L. Hanle OREGON JULY 14, 1978

WILLIAM L. HANLEY 1639

for record on the day of
State ofOregon, I hereby certify that the within instrument was filed in this office.
Office of County Surveyor County of Union

...... by .......

(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR

Z

### **AMENDED** CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## History of original corner establishment:

Corner established by Henry Meldrum under GLO Contract No. 450 and dated June 11, 1882.

Surveyor General records state?

Basalt stone 18 x 10 x 7 ins, 12 ins in ground for Cor to Secs 13, 14, 23 & 24, marked with 3 notches on S and 1 on E edge on top of hill from which:

A pine 26" dia brs N12°W, 66 1ks dist mkd R40ES14 BT.

A pine 15" dia brs S51°W, 86 1ks dist mkd S23 BT.

A pine 26" dia brs S56°E, 86 1ks dist mkd S24 BT.

A pine 6" dia brs N07°E, 62 1ks dist mkd T2SS13 BT.

N-21		
DIAGRAM		
T 2 S	R 40 E	
S 14	S 13	
S 23	S 24	
1987		
ORLS	1639	

### Description of corner evidence found:

A stone 20 x 10 x 7 ins(record, 18 x 10 x 7 ins) in place on surface marked with 3 notches on the S face and 5 notches on the W face (record, 1 notch on E face) from which:

Rotten pine log 24" dia brs Nl2<sup>O</sup>W, 66 lks dist per record, no marks identified. Rotten pine log 24 ins dia brs S5l<sup>O</sup>W, 86 lks dist per record, no marks. Pine log 20 ins dia brs S56<sup>O</sup>E, 86 lks dist per record with "S24 BT" scribes visible in chopped open double blaze. No trace of section 13 BT.

# Description of monument and accessories I established to perpetuate the original location of this corner:

At position of found stone ...

Set  $2\frac{1}{2}$ " aluminum cap on 2" aluminum pipe 25" in ground & 5" projecting out of ground with surrounding rock mound & 6' fence post alongside with sign 54-9 attached. Cap marked as shown in corner diagram. Buried stone alongside.

New bearing trees established:

A 18" lodgepole pine brs N48°E, 45.1' mkd T2SR40ES13 BT. A 18" lodgepole pine brs S25°E, 52.0' mkd T2SR40ES24 BT. A 15" lodgepole pine brs S42°W, 45.0' mkd T2SR40ES23 BT. A 15" lodgepole pine brs N49°W, 36.3' mkd T2SR40ES14 BT.

New BT's have brass washer stamped PLS 1639 nailed to face of blaze. Attached signs 54-3 & 54-9 and painted face of blaze and 6" band of red around each BT. Set 6' steel fence post alongside of corner and attached sign 54-9.

Compass declination 170 East.

I hereby certify that the above described corner monument was properly remonumented by me and witnessed by Jim DeMastus on August 10, 1987.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 14, 1978 WILLIAM L. HANLEY

William

1639

Office of Country Surveyor	County of Union	
State of Oregon , I hereby certify	that the within instrument was filed in this office	
for record on the day of		
(COUNTY OFFICIAL)	(DEPUTY)	

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR

9 22-88 nin €320 v66 1-971, 1988

12.0