CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by Henry Meldrum under GLO contract No. 450 and dated June 11, 1882. Surveyor General records state: Set post 4 ft long 4 ins square 24 ins in ground for Cor to Secs 24,25, 19 & 34 mkd T2SR40ES24 on NW, R40ES25 on SW, R41ES30 on SE and S19 on NE with 2 notches on S and 4 on N edge from which: A fir 12" dia brs N43 E, 58 lks dist mkd S19 BT. A tamarack 30" dia brs N56 W,50 lks dist mkd T2SS24 BT. A tamarack 16" dia brs S45 W,61 lks dist mkd R40ES25 BT. A tamarack 9" dia brs S68 E, 17 lks dist mkd R41ES30 BT.

	R-25		
	DIAGRA T 2 S		
	S 24	R 41 E	
	S 25 R 40 E	S 19	
,	1987		
3	ORLS	1639	

Corner MODIFIED by Alonzo Gesner under GLO contract No. 683 dated June 17,1898, and his records state: The Cor to Secs 24 and 25 which is a post marked and witnessed as stated by the U.S. Survey General I destroyed the marks on the NE and SE faces of post and obliterated marks on the bearing trees in Secs 19 and 20.

Description of corner evidence found:

No trace of original post corner.

A rotten tamarack stump with burned face mkd R40ES25 BT, on double blaze alongside brs S44 $^{\rm O}$ W, 61 lks dist per record. A green tamarack 40" dia with healed double blaze and ancient axe marks on bark brs N52 $^{\rm O}$ W(record, N56 $^{\rm O}$ W), 50 lks dist. No trace of other two BTs obliterated by Alonzo Gesner in 1898.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position established by record distance intersection from found original BT's...

Set $2\frac{1}{2}$ " aluminum cap on 2" aluminum pipe 20" in ground & 10" projecting out of ground with surrounding earth mound & 6' fence post alongside with sign 54-9 attached. Cap marked as shown in corner diagram.

New bearing trees established: A 8" alpine fir brs $\rm S64^{\circ}W$, 18.3' dist mkd T2SR40ES25 BT.

Each BT has a sign 54-3 and signs 54-4 or 54-9 attached below a 6" band of red paint, and each new BT has a brass washer marked PLS 1639 nailed flush with BT blaze.

Compass declination 170 East.

Form

I hereby certify that the above described corner monument was properly remonumented by me and witnessed by Jim DeMastus on August 10, 1987.

REGISTERED PROFESSIONAL LAND SURVEYOR William L Harley OREGON JULY 14, 1978

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of County Surveyor C State of Oregon I hereby certify that	ounty ofUnion the within instrument was filed in to	his office
for record on the day of by (COUNTY OFFICIAL)	, 19	UNION COUNTY
R6-7100-57 (9/71)	(DEPUTY)	Osto Received 9-1-87
		Date Filed 9-16-87