CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by Henry Meldrum under GLO contract No. 450 and dated June 11, 1882. Surveyor General records state: Set post 4' long 4" square 24" in ground for Cor to Secs 25,36,30 & 31 mkd T2SR40ES25 on NW, S30 on NE, R41ES31 on SE and R40ES36 on SW with 1 notch on S and 5 notches on N
edge from which: A pine 16" dia brs N35 E,35 lks dist
mkd S30 BT. A pine 20" dia brs N36 W,56 lks dist mkd
T2SR40ES25 BT. A pine 10" dia brs S5 W,45 lks dist mkd
R40ES36 BT. A fir 24" dia brs S10 E, 17 lks dist mkd
R40ES36 BT. A fir 24" dia brs S10 E, 17 lks dist mkd
R40ES36 BT. Corner reestablished by Alonzo Gesner under GLO contract No. 683 dated June 7, 1898. His

AM SIT2S
T 2 S
S 30
.987
5 1639

records state: Cor to Secs 25 & 36 T2SR40E, which had been destroyed which I reestablished... Set basalt stone 18 x 8 x 7in 12 ins in ground mkd with 1 notch on S & 5 notches on the N sides from which: A tamarack 14" dia brs N31 30'W,191 lks dist mkd T2SR40ES25 BT. No other trees in limits or convenient to mark in Sec 36. Raised mound of stone 3' base $2\frac{1}{2}$ ' high 10 lks West of corner.

Description of corner evidence found:

Found a stone 18 x 7 x 5"(record, 18 x 8 x 7") no marks positively identified, 10 lks east of remnants of manmade rock mound from which:

A tamarack windblow 15" dia and root stub mkd with fragmentary scribes on open & rotting blaze brs $N31\frac{1}{2}^{O}W$, 191 lks per record. No other tree found by Gesner.

UNION COUNTY SURVEYOR

Description of monument and accessories I established to perpetuate the original location of this corner:

At position of record sized stone...

Set $2\frac{1}{2}$ aluminum cap on 2 aluminum pipe 25 in ground & 5 projecting out of ground with surrounding rock mound & 6' fence post alongside with sign 54-9 attached. Cap marked as shown in corner diagram. Buried stone alongside. REMARKS: This corner is on top edge of vertical rocky bluff 30' high.

New bearing trees established: A tamarack ll" dia brs $S05\frac{1}{2}^{0}W$, 43.4' dist mkd T2SR40ES36 BT. A tamarack ll" dia brs $N46\frac{1}{2}^{0}W$, 41.8' dist mkd T2SR40ES25 BT.

Each BT has a sign 54-3 and signs 54-4 or 54-9 attached below a 6 " band of red paint, and each new BT has a brass washer marked PLS 1639 nailed flush with BT blaze.

Compass declination 17° East.

I hereby certify that the above described corner monument was properly remonumented by me and witnessed by Jim DeMastus on August 13, 1987. Jun Dellastue

REGISTERED **PROFESSIONAL** LAND SURVEYOR

William L. Horley

OREGON JULY 14, 1978 WILLIAM L. HANLEY 1639

Office of County Surveyor County of Union State of.....Oregon ..., I hereby certify that the within instrument was filed in this office by (COUNTY OFFICIAL) (DEPUTY)