## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## History of original corner establishment:

None. Corner established with this survey.

X-19		
DIAGRAM T 2 S R 40 E	•	
$C = \frac{1}{4} - S = 35$		
1989		
ORLS 1639		

## Description of corner evidence found:

None.

NOTE: A 5" diam fir brs S24°E, 61' dist from corner position established during this survey as dsecribed below with a Boise Cascade Corp. location tag attached marked "center of section" dated May 15, 1974, and initialed by GA/DB. Trees with red painted blazes run South & West from this recovered tree. No record of official survey for proper placement of this tag was found!

## Description of monument and accessories I established to perpetuate the original location of this corner:

At position established by proper subdivision of section from survey control...

Set a 2" x 30" aluminum pipe with  $2\frac{1}{2}$ " aluminum cap 24" in ground & projecting 6" out of ground with surrounding stone mound & placed 6' steel fence post alongside with signs 54-2 & 54-9 attached. Cap marked as shown in corner diagram.

New bearing trees established: White fir 10" dia brs S56°E, 16.5' dist mkd C 1/4 S 35 BT. Red fir 29" dia brs N47 $\frac{1}{2}$ °E, 41.4' dist mkd C 1/4 S 35 BT.

New bearing trees have a brass washer marked PLS 1639 nailed flush to face of blaze. Attached signs 54-3 & 54-9 & painted face of blaze & a 6' band of red around each bearing tree.

Compass declination 190 East.

I hereby certify that the above described corner monument was properly established by me & witnessed by Patti Hanley on July 22, 1989.



Office of County Surveyor County of Units	
fer record on the day of	
Form R6-7100-57 (9/71)	*GPO-591-971, 1988

X-19