CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File Number J-19

History of original corner establishment:

Corner was originally established under G. L. O. contract number 498, by Frank W. Campbell, during May 19, 1884.
Surveyor General's notes state: "Set basalt stone, 10 X 10 X 10 ins., 7 ins. in the ground, for 1/4 sec. cor. mkd. 1/4 on N. face; from which: A ir, 10 ins. diam., bears N. 6° E., 22 lks. dist., marked 1/4 S BT. A tamarack, 20 ins. diam., bears S. 32° E., 28 lks. dist., mkd. 1/4 S BT."

DIAGRAM T3N R39E Sll 1/4-S14

Description of corner evidence found:

Found down and rotten 20" tamarack, scribed 1/4 S. At part of stump, found piece scribed BT. Measured N32°W, 18.5 ft. Found no trace of record stone or northeast bearing tree.

Description of monument and accessories I established to perpetuate the original location of this corner:

At measured point, set 2 1/2" X 30" aluminum pipe and cap marked:

Set pipe 24" in the ground and mound of stone around to cap.

S14 · OR PLS 1051 From which: 1984 An 8" Tamarack bears N37 1/2°E, 29.5 ft. scribed 1/4 Sll

BT. A 6" Tamarack bears S60°E, 47.1 ft. scribed 1/4 S14 BT. Painted blazes red and 6" red band around. Placed 54-3s, 54-4s and brass washers stamped PLS 1051 on the bearing trees. Placed 54-4 on a steel fence post 5' east of the corner.

Corner falls near a north-south fence, 20' south of the fence corner.

REGISTERED **PROFESSIONAL** LAND SURVEYOR

13aci OREGON OCT. 17, 1975 BARRY B. BARBOUR 1 0 5 1 I hereby certify that the above corner monument was reestablished as herein described.

T3N R39E

Sll

Witness: Robert W. Wilson

October 9, 1984.

Office of	CountySurv	reyor	. County of	Union			••••
State of	Oregon/	hereby certify th	at the within in	strument was	fil ed in this	of	fica

for record on the...... day of....November......, 19.84

.....by (COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR

Date Received 11-19-84

Date Filed 12-4-

By G. LANGLITZ

File No. 1042-84 R

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner established by Frank W. Campbell under GLO contract No. 498 dated March 10th, 1884. Surveyor General's notes state:

Set basalt stone, 10x10x10 ins,. 7 ins. In the ground, for 1/4 sec. cor. mkd. 1/4 on N. face; from which: A fir, 10 ins. diam., bears N6°E, 22 lks dist. marked 1/4 S RT.

A tamarack, 20 ins. diam., bears S32°E 28 lks. dist. marked 1/4 S BT.

In Survey Number 53-84, Barry Barbour brings the corner to county standard from the found tamarack bearing tree. Union County Monumentation Record 1042-84R states:

Found down and rotten 20" tamarack, scribed 1/4S. At part of stump, found piece scribed BT. Measured N32°W, 18.5 ft. Found no trace of record stone or Northeast bearing tree. At measured point, set 2 1/2" x 30" aluminum pipe and cap marked as shown, set pipe 24" in the ground and mound of stone around to cap. From which:

An 8" Tamarack bears N37 1/2°E, 29.5 ft. scribed 1/4 S11 BT.

A 6" Tamarack bears S60°E, 47.1 ft. scribed 1/4 S14 BT. Corner falls near a North-South fence, 20' South of the fence corner

S 14

T3N R39EJ-19

DESCRIPTION OF CORNER EVIDENCE FOUND:

Found a 2 1/2" aluminum pipe with 2 1/2" aluminum cap, 5" above ground marked as shown below. From which:

A 12" Western Larch bears North 38° East a dist. of 29.50', alive and vigorous with healed blaze.

A 6" Western Larch bears South 60° East a dist. of 47.10', dead and standing with scribes visible on partially healed blaze. Fence post falls approx. 5' East.

See Survey Number 031-2021

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

From the aluminum pipe monument,

NEW BEARING OBJECTS:

An 8" White Fir bears South 56° East a dist. of 24.95' marked 1/4 S14 BT

A 15" White Fir bears South 24° West a dist. of 9.65' marked 1/4 S14 BT $\,$

An 8" Western Larch bears North 74° West a dist. of 6.50' marked 1/4 S11 BT $\,$

I hereby certify that the corner was perpetuated on June, $18\text{th}\ 2021$.

Witness: Kyle A. Tucker

T3N R39E

1/4 S11
S14
OR PLS 1051
1984

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2023

UNION COUNTY
SURVEYOR

Date Received 7 15 71

Date Filed 7 15 71

Filed By Mac Winn Deporty

File Number 625 - 201 R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.