CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1882 by Rufus S. Moore under General Land Office contract no. 451. Surveyor General Notes State;

Set basalt stone 13"x7"x6", 9 inches in the ground for the $\frac{1}{4}$ section corner, 300 feet above the creek, marked $\frac{1}{4}$ on the west face, from which

A pine 6 inches in diameter bears N 22 E 28 links, distant marked & S BT.

A fir 8^{H} in diameter bears S 60 W 56 links distant, marked $\frac{1}{4}$ S BT.

DIAGRAM T 3 S 1 R 35 E S 17 S 16

No remonumentation found in the county record.

Description of corner evidence found:

Found NE. BT. stump, rotted, with blaze lying alongside with scribes visible.

Found SW. BT. stump, scar visible, did not open.

I did not find the stone.

Description of monument and accessories I established to perpetuate the original location of this corner I set a $2\frac{\pm}{2}$ "x30" galvanized iron pipe with brass cap 18" in the ground and raised a mound of stone at the record distances and bearings from the BTs. from which

New BTS.

A pine 12" in diameter bears N 7 W a distance of 24.6 feet, marked $\frac{1}{4}$ S 17 BT.

A fir 10" in diameter bears S 30 $\mathbb R$ a distance of 43.0 feet, marked \$\frac{1}{4}S 16 BT.

I placed a nail and a brass washer marked O.P.L.S. 991 at the BT. blaze

I used a steel tape and magnetic compass with 20 degrees East declination set into the compass.

I set a steel fence post with a sign 4.0 feet south of the corner.

T 3 5 R 35 E 1/4 5 16 1978 PLS 991

	LAND SURVEYOR
•	Gregory T. Blackwar-
Office of Juny County of Union State of Oregon I hereby certify that the wishing to come the state of the st	OREGON BREJORY T. BLACKMAN 991
Office of County of UNION State of Crewin, I hereby certify that the within instrument was filed in this office- for record on the 18 day of Light, 1978 (COUNTY OFFIGIAL) LIGHTY (DEPUTY)	UNION COUNTY SURVEYOR
	Data Receivéd

Form R6-7100-57 (9/71)

REGISTERED **PROFESSIONAL**

Date Filed

413-84 R File No. GPO 796-333