CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by David P. Thompson under GLO contract number 103, dated September 3, 1863 Surveyor General record states:

Set post for 1/4 cor From Which:

A 40 inch Pine bears N 50° E, 8 lks. A 18 inch Pine bears S 82°W, 70 lks.

No record of subsequent monumentation found in Union County Survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Found Northeast bearing tree stump at record bearing and distance. Rotted, now a 30 inch stump, no scribes visible.

T3S R38EX-05

Found Southwest bearing tree stump at record bearing and distance. Rotted, now an 18 inch stump, no scribes visible

Found a small rock mound. Corner position falls approximately 18 feet southeast of the proportioned position.

See Survey No. 026-2002

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position as determined by the found bearing trees, I set a $2\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown, 25 inches in the ground and raised a mound of stone with a 2 foot base to top of cap, from which:

An 11" Ponderosa Pine bears North 24° East, 34.38 feet, marked 1/4 S32 BT

A 12" Ponderosa Pine bears South 71° East, 57.08 feet, marked 1/4 S32 BT

An 11" Douglas Fir bears South 20° West, 41.60 feet, marked 1/4 S31 BT

A 9" Ponderosa Pine bears North 55° West, 32.23 feet marked 1/4 S31 BT


I hereby certify that the above corner point was perpetuated as hereon described on July 12, 2002. Witnesses: Norbert W. Volny Gregory T. Blackman Jr.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON

GREGORY T. BLACKMAN 991

Renewal Date: December 31, 2003



UNION COUNTY
SURVEYOR

Date Received 1/19/62

Date Filed 1/19/62

Filed By R. ROBINSON, DEPUTY

File Number 0(5-2002)

I used a steel tape and magnetic compass in the establishment of new accessories. I used 18° East magnetic declination and the distances are to a 60d spike driven in the right side at the root crown or the center of aluminum cap. I attached a brass washer marked OPLS 991 to the BT Blaze.