CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by W.B.Barr under contract No. 355 and dated June 14, 1880.

Surveyor General records state: Marked a tamarack 18" diam for corner to Sec 1 x 6 x 7 x 12 from which: Fir 12 in dia brs 585° W, 12 lks dist. Fir 5" dia brs 584° W, 24 lks dis. Fir 4" dia brs 584° E, 13 lks dist. Pine 15" dia brs 510° E 83 lks dist.

E-25	
DIAGRAM	
т 3 ѕ	T 3 S
S 1	R 41 E
S 12	S 6
R 40 E 1987	
ORLS	1639

Corner REESTABLISHED by Alonzo Gesner under contract No. 683 and dated June 7, 1898, and his records state: The corto Secs 1 and 12 range 40 E which is a tree but destroyed by forest fires. I reestablished it as follows: Set basalt stone 20x10x5", 15" in ground mkd with 5 notches on the S and 1 notch on N side from which: A pine 18" dia brs N64 W,30 lks dist mkd T3SR40ES1 BT. A tamarack 20" dia brs S68 W,54 lks T3SR40ES12 BT. Note, the bearing trees (old survey) have been killed by forest fires.

Description of corner evidence found:

Found basalt stone 22 x 11 x 4"(record, 20 x 10 x 5") in place well marked with 5 notches on S and 1 notch on N $\,$ faces from which:

A tamarack 23" dia brs $S64\frac{1}{2}^{O}W$, 34.0'(record, $S68^{O}W$, 54 lks) with healed double blaze. A rotten root stub brs $N64^{\circ}W$, 30 lks per record with no

UNION COUNTY SURVEYOR	
Oars Received 9-1-87	
Dere Filed 9-16-87	
By G. LANGUITZ, DOPUTY	
FE: No. 102-87 R	

Description of monument and accessories I established to perpetuate the original location of this corner:

At position of found stone ...

Set $2\frac{1}{2}$ " aluminum cap on 2" aluminum pipe 25" in ground & 5" projecting out of ground with surrounding rock mound & 6' fence post alongside with sign 54-9 attached. Cap marked as shown in corner diagram. Buried stone alongside.

New bearing trees established: A tamarack 15" dia brs N47°W, 44.2' dist marked T3SR40ES1 BT.

Each BT has a sign 54-3 and signs 54-4 or 54-9 attached below a 6" band of red paint, and each new BT has a brass washer marked PLS 1639 nailed flush with BT blaze.

Compass declination 170 East.

I hereby certify that the above described corner monument was properly remonumented by me and witnessed by Jim DeMastus on August 20, 1987. Im O Masture

REGISTERED PROFESSIONAL LAND SURVEYOR	
William Z. Hor	lu
OREGON JULY 14, 1978 WILLIAM L. HANLEY 1639	

Office of County Surveyor	County of Union		
State ofOregon I hereby certify that the within instrument was filed in this office			
for record on the day of			
by			
(COUNTY OFFICIAL)	(DEPUTY)		