CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. R-8

History of original corner establishment: Not set.

DIAGRAM
T4N R4OE E <u>\$20</u> 1/16

Description of corner evidence found: None.

Corner falls near the Northwest corner of logged area and North of a fence corner.

Description of monument and accessories I established to perpetuate the

original location of this corner:

At surveyed point set $2\frac{1}{2}$ " x 30" galvanized pipe with brass cap marked: Set pipe 24" in the ground, and placed about five rocks around.

T4N R4OE S20 1/16 S29 OR PLS 1051 1978

File No. 62-83R

No other rock in the area.

From which: A Tamarac 10" in dia. bears N13°W, 12.5 feet scribed E1/16S2OBT. A Tamarac 12" in dia. bears S40°E, 58.3 feet scribed E1/16S29BT. Painted blazes red and 6" red band around. Placed 54-3s and 54-4s on BTs. Placed brass washer stamped PLS 1051 on foot blazes. Placed 54-2 and 54-9 on steel fence post 4! East and 54-2 and 54-4 on steel fence post 5! North of corner. Placed 54-5 on tree 10! North of corner.

REGISTERED **PROFESSIONAL** LAND SURVEYOR

garbour OREGON OCT. 17, 1975 BARRY B. BARBOUR 1 0 5 1

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses:

David L. Landers Dan T. Rowland

November 1, 1978

office of		
(COUNTY OFFICIAL)	(DEPUTY)	SURVEYOR
orm R6-7100-57 (9/71)		Tate Received
		Date Filed