CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. T-6

History of original corner establishment:

Not set.

DIAGRAM Т4И Д4ОЕ W1/16 S29

Description of corner evidence found:

None.

Corner falls near the NE corner of clear cut and South of drift fence.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set $2\frac{1}{2}$ " x 30" galvanized pipe with brass cap marked: Set Pipe 24" in the ground.

T4N R4OE W1/16 S29 $C \longrightarrow C$

No rock in the area.

OR PLS 1051 1978

File No. <u>83-83</u>R

A Fir 20" in dia. bears N79°E, 31.7 feet, scribed A Fir 14" in dia. bears S27°W, 24.0 feet, scribed Painted blazes red and 6" red band around. Place From which: WC1/16S29BT. WC1/16S29BT. 54-3s and 54-4s on BTs. Placed brass washer stamped PLS 1051 on foot blazes. Placed 54-2 and 54-4 on steel fence post 5' South and 54-2 and 54-9 on steel fence post 3' West of corner. Placed 54-5 on tree 3' West of corner.

REGISTERED **PROFESSIONAL** LAND SURVEYOR

2 soul OREGON OCT. 17. 1975 BARBOUR BARRY B. 1051

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses:

David L. Landers Dan T. Rowland

October 27, 1978

office of County Surveyor Co State of Oregon I hereby certify that to for record on the 20 day of November	he within instrument was filed in th	nis office
COUNTY OFFICIAL		UNION COUNTY SURVEYOR
orm R6-7100-57 (9/71)		Date Received
		Date Filed