


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. V-7

History of original corner establishment:

Corner established by Frank W. Campbell under G.L.O. Contract #507 in August, 1884. Surveyor's General's notes state: "Set Fir post 3 ft. long, 3 ins. square 24 ins. in ground for 1/4 Sec. corner marked 1/4 S. on N. face, from which: A Fir 12 ins. diam. bears N. 30° E. 117 lks. dist. marked 1/4 S.B.T.. A Fir 24 ins. bears S. 13° W. 35 lks. dist. marked 1/4 S.B.T.."



Description of corner evidence found:

No evidence of original corner could be found. A dilligent search was made before the survey and after the corner position was determined.

A location tag referring to the approximate position of -corner was located.

Corner falls at East tip of small meadow.

Description of monument and accessories | established to perpetuate the original location of this corner:

At single proportionate distance between the SE and SW corners of section 29 set 2 1/2" x 30" galvanized pipe with brass cap marked: Set pipe 25" in the ground.

T4N R40E  
1/4  $\frac{S29}{S32}$   
OR PLS 1051  
1978


No stone in the area.

From which: A Tamarac 32" in dia. bears N56°E, 116.3 feet, scribed 1/4S29BT. A Fir 26" in dia. bears S14°W, 44.5 feet, scribed 1/4S32BT. Painted blazes red and 6" red band around. Placed 54-3s and 54-4s on BTs. Placed brass washer stamped PLS 1051 on foot blazes. Placed 54-2 and 54-4 on steel fence post 4' North and 54-2 on steel fence post 3' West of corner. Placed 54-5 on snag 30' Southwest of corner.


I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: David L. Landers  
Dan T. Rowland

October 25, 1978



*Barry B. Barbour*



Office of.....County Surveyor..... County of.....Union.....  
State of.....Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the...20... day of...November....., 1978

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

FILED  
OCT 27 1978  
PLS 1051  
GPO 799-509  
FILE NO. 102-83R