
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None. Corner established as part of this survey.



Description of corner evidence found:

None.

UNION COUNTY SURVEYOR
Data Received 1-5-89
0 to Med 1-6-89
BY G. LANGLITZ DODUM
File No. 11 -89 R

Description of monument and accessories I established to perpetuate the original location of this corner:

At position established by survey...


Set a $2\frac{1}{2}$ " aluminum cap on $2\frac{1}{2}$ x 30" aluminum pipe 15" in ground, to bedrock, surrounded with mound of earth and stone & 6' steel fence post E & S of corner and attached sign 54-9 to one & 54-2 to both. Cap marked as shown in corner diagram.

New bearing trees established: A 12" ponderosa pine brs N30 $\frac{1}{2}$ °E, 37.9' scribed N1/16S14 BT. A 16" ponderosa pine brs S61 $\frac{1}{2}$ °W, 15.1' scribed N1/16S15 BT.

New BTs have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each BT.

Compass declination 190 East.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on October 24, 1988.



1106

REGISTERED

Office of County Surveyor	County of Union
Office of	
(COUNTY OFFICIAL)	by(DEPUTY)