


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

(A-3)

**History of original corner establishment:**

The original survey was performed by T. Davenport as part of the GLO Survey in 1863. The survey of the South boundary of T. 3 S., R. 38 E. was under contract #102. The GLO record states:



At the corner point a post was set, from which:  
A tamarack, 5 ins. diam., bears S. 60° E., 10 lks. dist.  
A pine, 30 ins. diam., bears N. 10° W., 65 lks. dist.

**Description of corner evidence found:**

Found a 32 ins. diam. ponderosa pine stump 42 ins. high, which has been sawed and burned. Part of the "T" is visible on the portion of the rotted blaze. No sign of the 5 ins. diam. tamarack.

**Description of monument and accessories | established to perpetuate the original location of this corner:**

Set a 1-inch x 30-ins. iron pipe with a 2½ ins. brass cap, 26 ins. in the ground, surrounded by a 36 ins. diam. stone mound. The cap is marked as shown on the above diagram. The corner was reestablished from the found bearing tree stump.

**New bearing trees:**

A ponderosa pine, 13 ins. diam., bears N. 50° E., 9.5 ft. dist., mkd ¼ S BT.  
A white fir, 16 ins. diam., bears S. 66° E., 2.2 ft. dist., mkd ¼ S BT.

Set a steel fence post alongside the monument, painted the blazes and the scribes on the bearing trees red.

I certify the above monument and references were properly reestablished under my supervision on May 29, 1986, and witnessed by Tom Fisk and Larry McBroom.

<b>UNION COUNTY SURVEYOR</b>	
Date Received <u>5-1-89</u>	
Date Filed <u>5-15-89</u>	
By <u>G. LANGRIZ, DEPUTY</u>	
File No. <u>111-89 R</u>	

<b>REGISTERED PROFESSIONAL LAND SURVEYOR</b>
<i>James D. Hanley</i>
OREGON SEPTEMBER 23, 1977 JAMES D. HANLEY 1206

Office of..... County of.....  
 State of....., I hereby certify that the within instrument was filed in this office  
 for record on the..... day of....., 19.....  
 ..... by .....  
 (COUNTY OFFICIAL) (DEPUTY)