## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original survey by W. Barr, 1881, states:

Marked basalt rock, 14x10x5 for 1/4 Sec. corner

From which:

Pine 14 in. diam. bears North 59 lks. dist.

Fir 6" diam. bears S15°W 69 lks. dist.

DIAGRAM
TAS R38E

1/4 - 4 - 23

Description of corner evidence found:

 $\frac{Found}{find}$  Original SW BT a downed Fir, 18" diam., we open and find scribing "/4S"

No other evidence found

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner point determined by reference to the only remaining original BT, we set a 2"x30" Galvanized Iron Pipe, 22" in the ground and raise mound of stone around monument, with brass cap attached, marked:

T4S R38E

From which the stump hole of the original BT bears  $$15^{\circ}W$ 45.5 ft.$ 

1/4 S23

and new accessories:

PLS 1099

An 8" Douglas Fir, scribed "1/4 S23 BT" on a double blaze bears S20°W 79.5 ft.

1981

An "+BO" chiseled at the bottom of a vertical bedrock face, approximately 30 ft. wide and 15 ft. high bears N 77 1/2° W. 22.8 ft.


Attached brass washer, marked "LS 1099" to lower blaze of new BT. Placed steel fencepost and "ATTENTION" sign alongside corner monument. Corner is located approximately 120 ft. West of Eastbound lane I-84 about 1/4 mile south of Ladd Creek exit.

Compass Declination: 20° East

Witnesses: Gary L. Langlitz PLS 1099

David Allen

Form R6-7100-57 (9/71)



REGISTERED