


# CORNER RECORD

Town of \_\_\_\_\_ County of \_\_\_\_\_ Union \_\_\_\_\_, Oregon  
Brief Legal Description Center 1/4 corner of Section 4, Township 4 South, Range 39 East, Willamette Meridian.



### CORNER TYPE

Government Corner  Control   
Meander  Property   
D.L.C.  Other   
Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. 586104.05  
E. 8860620.35  
Zone OR N NAD27  NAD83

Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Set 5/8" rod with red plastic cap stamped "NORTHSTAR PLS 1823" at the center 1/4 corner, established by intersection between the found N, W, & E 1/4 corners. along with a computed location of the S 1/4 corner that was calculated by proportionate measurements between the south west and southeast section corners of said Section 4. See map of survey No. 006-2013

A description of the physical condition of the monument as found and as set or reset: At a position set by survey, I set a 5/8" x 30" rebar with red plastic cap stamped "NORTHSTAR PLS 1823" buried 18" in the plowed field, from which: Two 5/8" x 30" rebar bearing N 89°55'31" W at 434.00 and 867.99 feet, with red plastic cap stamped "NORTHSTAR PLS 1823." Also two 5/8" x 30" rebar bearing N 00°26'57" E at 455.96 and 911.84 feet, with red plastic cap stamped "NORTHSTAR PLS 1823"

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction,  
on \_\_\_\_\_ 20 \_\_\_\_  
Signed \_\_\_\_\_ P.L.S. No. 1823

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Theodore James Langton*  
OREGON  
JULY 13, 1979  
THEODORE JAMES LANGTON  
1823

RENEWS: 12/31/2014

### UNION COUNTY SURVEYOR

Date Received 2/29/13  
Date Filed 2/31/13  
By [Signature]  
File No. 005-2013R