


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original survey by T. Davenport under GLO contract 102, 1863.
Set Qr. Sec. post from which a Tamarack 20" dia. bears N70°W
6 lks. dist.
A White Fir 6" dia. bears S70°E 6 lks. dist.



Description of corner evidence found:

Remains of a decayed wood post extending 18" below ground at the corner point.
And the original BT's:
A Tamarack stump decayed at Ground level, approx, 20" dia.
And a Grand Fir, 28" dia. alive with well-healed double blaze

Description of monument and accessories established to perpetuate the original location of this corner:

At the corner point determined at the location of the rotted wood post, we set a 2"x30" Galvanized Iron Pipe 22" in the ground with brass cap attached, marked:

From which:

The original BT's:

A decayed "Tamarack" (Western Larch) stump, approx 20" dia. at ground level, bears N70°W 4.0 ft to face (4.8 ft. to center)
And a 28" Grand Fir bears S70°E 4.0 ft. to original face (4.5 ft. to center).


We Mark New BT's as Follows:

A 12" Western Larch, scribed "‡ S36 BT" on a double blaze bears N22°E 67.4 ft.
And a 14" Douglas Fir scribed "‡ S1 BT" on a double blaze bears S80½°W 16.0 ft..
Attached brass washer marked "LS 1099" to lower blaze of new BT's.
Horizontal dist. and bearings measured to center of tree root crown at ground level.
Magnetic Compass (20½° East Declination)
Steel Tape

	T3S	
‡	<u>S36</u>	R
	S1	40
	T4S	E
PLS	1099	
	1983	

June 16, 1983

Witnesses: Gary Langlitz
Dick Humiston



Office of..... County of.....
State of..... I hereby certify that the within instrument was filed in this office
for record on the..... day of..... 19.....

(COUNTY OFFICIAL)

UNION COUNTY
SURVEYOR
(DEPUTY)

Date Received 8-18-83

Date Filed 8-18-83

By G. LANGLITZ DEPUTY

File No. 320-83 R