CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. P-23

History of original corner establishment:

The original subdivision of T4S, R34E was by Rufus S. Moore under Contract No. 451, approved Feb. 1, 1884. But this was not an original GLO corner.

DIAGRAM

T5S R34E

C 1/4 · S 24

Description of corner evidence found:

No monument or evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 8" above ground. Cap is stamped: Set steel fence post 3.0 ft. north of corner.

T5S R34E

C1/4.S 24

RLS 1844 1984

New BT's:

A 6" L. Pine bears S50°E, 18.2 ft., blazed and scribed: C 1/4 S24 BT.

A 7" L. Pine bears N20°W, 11.2 ft., blazed and scribed: C1/4 S24 BT.

Brass LS 1844 disc in lower end of blaze. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found in dense thicket just off southeast corner of clearing from CN 1/16. Road 5160-544 to Fly Creek. Walk South from CN 1/16.

I hereby certify the above described corner monument and/or accessories was established as described on June 23, 1984.

REGISTERED PROFESSIONAL LAND SURVEYOR

> O M E G O N JULY 13, 1979 DAVID E. SCOTT 1844

Office of	County of
State of, I hereby certify for record on the day of	that the within instrument was filed in this office UNION COUNTY
b	y
(SOCIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

Date Filed of Don 24-84

By G. LANGLITZ, DEPUTY

File No. 956-84 R.