


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. P-07

History of original corner establishment:

This is not an original G.L.O. corner.



Description of corner evidence found:

No corner evidence found.

Description of monument and accessories established to perpetuate the original location of this corner:

Cap is stamped:

Corner set by intersection.

T5S R35E

Set 2.5" aluminum cap on 2"x30" aluminum pipe rising 4" above ground. Set steel fence post 3.0 ft. west of corner.

C 1/4 S20

RLS 1844
1984

New BT's:

9" Tamarack bears S84°W, 44.5 ft., blazed and scribed: C 1/4 S20 BT.

9" Tamarack bears S72°E, 31.5 ft., blazed and scribed: C 1/4 S20 BT.


Attached brass disk stamped LS 1844 to base of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Corner is found on north slope, 50 ft. elevation below ridge top. From the end of road 5155-084, go north 1000 ft. to posted line, then east about 200 ft. to corner.

Compass Declination: 19 1/2°E

Witness: Jeff Sheets

I hereby certify the above described corner monument and/or accessories was established as described on November 7, 1984.



Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR
Received <u>1-23-85</u>
☆ GPO-798-276
Filed <u>2-5-85</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>7-85 R</u>