


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This is not an original GLO corner.

Index File No. Q-22



Description of corner evidence found:

No corner monument or other evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner set by double proportioning.  
Set 2.5" aluminum cap on 2.5"x30" aluminum pipe rising 6" above ground. Set steel fence post 3.0 ft. East of corner.

Cap is stamped:

T5S R35E  
SW1/16•S24  
RLS 1844  
1985

New BT's:

7" Tamarack bears N59°E, 17.3 ft.,  
blazed and scribed: SW 1/16 S24 BT.

7" Tamarack bears S6 3/4°W, 10.0 ft.,  
blazed and scribed: SW 1/16 S24 BT.


Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "LS 1844" nailed to lower end of blazes.

Corner is found 50 ft. east of Road 5100-229 and 110 ft. east of fence. Take Road 5100-223 0.6 miles to Road 5100-229.

Compass Declination: 19 1/2°E

Witness: Bernie Sutton

I hereby certify the above described corner monument and/or accessories was established as described on May 5, 1985.



Office of..... County of.....  
State of....., I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

(DEPUTY)

**UNION COUNTY SURVEYOR**  
Date Received 9-18-85  
Date Filed 9-23-85  
By G. LANGLITZ, DEPUTY  
File No. 60-85 R