


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This is not an original GLO corner.

Index File No. R-22



Description of corner evidence found:

No corner monument or evidence found.

Description of monument and accessories established to perpetuate the original location of this corner:

Cap is stamped:

Corner set by single proportioning.
Set 2.5"X30" aluminum capped aluminum pipe rising 8" above ground. Set steel fence post 3.0 ft. north of corner.

T5S R35E
W 1/16 $\frac{S 24}{S 25}$

New BT's:


- 7" P. Pine bears N74.75°W, 46.3 ft., blazed & scribed: W1/16 S24 BT.
- 6" P. Pine bears S26.75°W, 19.9 ft., blazed & scribed: W1/16 S25 BT.

RLS 1844
1985

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "LS 1844" nailed to lower end of blazes.

Corner is 100' above and northwest of Road 51, 600' south of intersection with Road 5125 on steep, rocky, south slope.

Compass Declination: 19 1/2°E
Witness: Bernie Sutton



I hereby certify the above described corner monument and/or accessories was established as described on May 7, 1985.

Office of..... County of.....
 State of..... I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR
Date Received <u>9-28-85</u>
Date Filed <u>9-28-85</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>66-85 R</u>