## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This is not an original GLO corner.

Index File No.	s-	19
DIAGRAM T5S R35E		
C N1/16 <b>∤</b> S26		
С		

Description of corner evidence found:

No corner monument or other evidence found.

Description of monument and accessories I established to perpetuate the

original location of this corner:

Cap is stamped:

Corner set by subdivision. Set 2.5"x30" aluminum capped aluminum pipe rising 6" above ground. Set steel fence post 3.0 ft. north of corner.

**S26** N1/16**RLS 1844** 1985

T5S R35E

New BT's:

7" Fir bears N38.25°W 5.5 ft. blazed and scribed: CN1/16 S26 BT. 6" P. Pine bears N71.5°W, 15.0 ft., blazed and scribed: CN1/16 S26 BT.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "LS 1844" nailed to lower end of blazes.

Corner is in timber 30' south of intersection of Roads 5100-290 and 5100 5100-233. Take Road 51 to Road 5100-295 through fence, past pond to Road 5100-290, then east to corner. REGISTERED

Compass Declination: 19 1/2°E Witness: Herb Hamerlynck

I hereby certify the above described corner monument and/or accessories was established as described on May 3, 1985.

OREGON JULY 13, 1979 B. A. SUTTON 1 8 4 8

**PROFESSIONAL** 

SURVEYOR

Office of	ounty of	
State of		UNION COUNTY SURVEYOR
(COUNTY OFFICIAL)	(DEPUTY)	
Form R6-7100-57 (9/71)		Date Received 9-18-85  ***GPO-798-276  Date Filed 9-23-85