


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. S-20

History of original corner establishment:

Not an original GLO corner.



Description of corner evidence found:

No corner monument or evidence found.

Description of monument and accessories established to perpetuate the original location of this corner:

Corner set by subdivision.
Set 2.5"x30" aluminum capped aluminum pipe rising 10' above ground. Set steel fence post 3.5 ft. west of corner.

Cap is stamped: T5S R35E
NE1/16•S26
RLS 1844
1985

New BT's:


- 8" Tamarack bears N36.5°E, 140.3 ft., blazed and scribed: NE 1/16 S26 BT.
- 8" Tamarack bears N82°W, 138.2 ft., blazed and scribed: NE 1/16 S26 BT.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "LS 1844" nailed to lower end of blazes.

Corner is in fence line clearing 36.4 ft. south of fence, 70 ft. west of fence corner. Take Road 51 to Road Road 5100-290, then west to fence. South 400 ft. to corner.

Compass Declination: 19 1/2°E
Witness: Gary Arrand

I hereby certify the above described corner monument and/or accessories was established as described on May 3, 1985.



Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR
Date Received 9-18-85
Date Filed ^{☆ GPO 798,276} 9-23-85
By G. LANGLITZ DEPUTY
File No. 68-85 R